



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CARAVELLE T30 SWB W/V 130TDI
Colour	Silver
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	16.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-07
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-14
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	39
Total items failed	4

MOT #18	2024-04-15 14:04
MOT test number	824363153599
Result	✓ Passed
Next expiry date	2025-04-14
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Front Tyre worn close to legal limit/worn on edge O/S AND N/S (5.2.3 (e))

MOT #17	2023-04-03 11:15
MOT test number	780899655894
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Shock absorbers has light misting of oil both sides (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement rear bushes on arms (5.3.4 (a) (i))

**MOT #16**

2023-04-03 11:15

MOT test number

855029051027

Result**✗ Failed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement rear bushes on arms (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Shock absorbers has light misting of oil both sides (5.3.2 (b))**MOT #15**

2022-04-01 11:48

MOT test number

907616820382

Result**✓ Passed****Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14**

2022-03-24 11:24

MOT test number

197093796913

Result

✗ Failed

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #13**

2021-03-05 09:31

MOT test number

517238981383

Result

✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Central Exhaust silencer slightly loose outer skin peeling but not blowing (8.1.1 (b) (i))**MOT #12**

2020-03-25 15:22

MOT test number

825425068116

Result

✓ Passed

MOT #11

2019-03-18 10:16

MOT test number

741869513550

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn to outer edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2018-03-08 14:56**MOT test number** 778511950180**Result** ✓ Passed**MOT #9** 2017-03-24 12:39**MOT test number** 987726060188**Result** ✓ Passed**MOT #8** 2017-03-24 12:39**MOT test number** 607038725039**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #7** 2016-03-11 09:29**MOT test number** 238670834531**Result** ✓ Passed**Advice** Wipers slightly smearing**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2015-03-13 14:33**MOT test number** 695122475058**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Exhaust back box and middle box corroded

**MOT #5** 2014-03-29 09:42**MOT test number** 169938784454**Result** ✓ Passed

- Notice** Rear bumper damaged
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Sills part obscured by trims
- Notice** Nearside rear spring locator insecure
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #4 2013-03-16 09:55**MOT test number** 179545973019**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-03-24 09:17**MOT test number** 248614182093**Result** ✓ Passed**MOT #2** 2011-03-16 16:40**MOT test number** 937395971065**Result** ✓ Passed



MOT #1	2010-04-01 11:07
MOT test number	171281190497
Result	✓ Passed
Advice	Front brake disc slightly pitted (3.5.1h)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
14 April 2025

Tax status		Valid until 1 October
Days left		154
MOT expiry date		14 April 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RJ07UVK
Plate since	2024-03-28
Current registration	 RJ07UVK
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-10
Last registration	2024-04-15
Complete history	See info



Registration #1	2007-05-10	23 mi
Registration #2	2010-04-01	121.758 mi
Registration #3	2011-03-16	150.130 mi
Registration #4	2012-03-24	158.216 mi
Registration #5	2013-03-16	167.735 mi
Registration #6	2014-03-29	177.435 mi
Registration #7	2015-03-13	186.683 mi
Registration #8	2016-03-11	197.786 mi
Registration #9	2017-03-24	206.386 mi
Registration #10	2017-03-24	206.386 mi
Registration #11	2018-03-24	206.386 mi
Registration #12	2019-03-24	206.386 mi
Registration #13	2020-03-24	206.386 mi
Registration #14	2021-03-24	206.386 mi
Registration #15	2022-03-24	206.386 mi
Registration #16	2023-03-24	206.386 mi
Registration #17	2024-03-24	206.386 mi
Registration #18	2025-03-24	206.386 mi
Registration #19	2026-03-24	206.386 mi
Registration #20	2027-03-24	206.386 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2242 mm
Height	1969 mm
Length	4890 mm
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	BNZ 050185