





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I10 PREMIUM SE
Colour	White
Year of manufacture	2016
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	86 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	68.9 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-28
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	9
Total items failed	1

MOT #9		2024-01-19 14:24
MOT test	number	755020202089
Result		✓ Passed
Next expiry date 2025-01-2		2025-01-28
Advice Nearside Front Brake disc worn, but not excessively and offside (1.1.14 (a) (i))		
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (2	1.1.14 (a) (ii))

MOT #8		2024-01-19 12:07
MOT test	number	900065198882
Result		× Failed
Advice Nearside Front Brake disc worn, but not excessively and offside (1.1.14 (a) (i))		
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))		

MOT #7	2023-01-20 14:20
MOT test number	839169304052
Result	✓ Passed
Advice Nearside Front Brake disc worn, but not excessively and offside (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6 2023-01-20 12:41

MOT test number 613641794926

Result × Failed

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

Advice

Nearside Front Brake disc worn, but not excessively and offside (1.1.14 (a) (i))

MOT #5 2022-01-19 10:30

MOT test number 779216333135

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2021-01-29 12:33

MOT test number 809876246062

Result \rightarrow Passed

MOT #3 2020-05-19 11:26

MOT test number 802276958928

Result ✓ Passed

MOT #2 2019-05-01 07:50

MOT test number 275700226274

MOT #1 2019-05-01 07:50

MOT test number 792272330821

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4

(b) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
THE STATE OF THE S	

THE PERSON NAMED IN COLUMN TO THE PE	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	AIR AIR AIR
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-05-04
Last registration	2024-01-19
Complete history	See info



Registration #1	2016-05-04	28 mi
Registration #2	2019-05-01	27.275 mi
Registration #3	2019-05-01	27.275 mi
Registration #4	2020-05-19	33.491 mi
Registration #5	2021-01-29	36.687 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		11.177 es

More info >

CarCheck.co.uk page 10/11




WG1600U report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	941 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number G4LAGM913336