



report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC TDCI
Colour	Red
Year of manufacture	2009
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-24
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-11
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	5
Total items failed	8

MOT #16	2023-09-12 11:09
MOT test number	850666331691
Result	✓ Passed
Next expiry date	2024-09-11

MOT #15	2022-06-27 13:50
MOT test number	251178548788
Result	✓ Passed

MOT #14	2021-07-23 13:25
MOT test number	598171756045
Result	✓ Passed

MOT #13	2020-10-07 15:25
MOT test number	459960245150
Result	✓ Passed

**MOT #12** 2020-10-01 08:18**MOT test number** 465381262597**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #11** 2019-10-08 09:26**MOT test number** 592158767141**Result** ✓ Passed**MOT #10** 2018-09-24 16:07**MOT test number** 124497826904**Result** ✓ Passed**MOT #9** 2018-09-24 09:13**MOT test number** 868871930996**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 195601588h (5.2.3 (e))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #8** 2017-10-05 09:22**MOT test number** 938517727166**Result** ✓ Passed

**MOT #7** 2016-09-30 09:34**MOT test number** 960666781746**Result** ✓ Passed**Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Rear discs worn**MOT #6** 2015-10-24 08:43**MOT test number** 449614890209**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-12-23 15:17**MOT test number** 258477154368**Result** ✓ Passed**MOT #4** 2014-01-06 16:57**MOT test number** 415856904013**Result** ✓ Passed**MOT #3** 2014-01-06 16:57**MOT test number** 496986904098**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2013-06-21 13:14**MOT test number** 926662073111**Result** ✓ Passed



MOT #1	2012-06-22 09:52
MOT test number	136274472167
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
11 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	11 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-28
Current registration	 *****
Plate since	2023-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-08-07
Last registration	2023-09-12
Complete history	<a href="#">See info</a>



Registration #1	2009-08-07	22 mi
Registration #2	2012-06-22	12.746 mi
Registration #3	2013-06-21	16.863 mi
Registration #4	2014-01-06	19.319 mi
Registration #5	2014-12-23	28.640 mi
Registration #6	2015-10-24	36.556 mi
Registration #7	2016-09-30	43.579 mi
Registration #8	2017-10-05	52.335 mi
Registration #9	2018-09-24	61.961 mi
Registration #10	2019-09-20	71.577 mi
Registration #11	2020-09-20	81.193 mi
Registration #12	2021-09-20	90.809 mi
Registration #13	2022-09-20	100.425 mi
Registration #14	2023-09-20	110.041 mi
Registration #15	2024-09-20	119.657 mi
Registration #16	2025-09-20	129.273 mi
Registration #17	2026-09-20	138.889 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1162 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9R24978