





report date: 2024-03-29

General information

Make	ТОУОТА
Model	GT86 D-4S
Colour	Grey
Year of manufacture	2013
Top speed	140 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	205 Nm at 6.400 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	181 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-29


Internet history

Entry 2

Date 2021-12-14

Pictures 31

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


Date 2021-12-13

Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-10
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #12	2024-01-09 09:59
MOT test number	910350697439
Result	✓ Passed
Next expiry date	2025-01-10

MOT #11	2023-01-11 08:53
MOT test number	656036736954
Result	✓ Passed

MOT #10	2022-01-10 15:33
MOT test number	909868850342
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #9	2021-09-13 14:27
MOT test number	732205132373
Result	✓ Passed
MOT #8	2020-09-15 09:44

MOT test number	124214567879
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2020-08-21 14:16 **MOT** test number 510052517169 Result **X** Failed **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Offside Rear Nail in tyre Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #6	2019-08-23 14:42
MOT test number	733665168702
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #5		2018-07-31 15:51
MOT test	number	563055495314
Result		✓ Passed
Advice	Front brake pads starting to get low	
Advice	Nearside washer jet blocked	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4

MOT test number

Result

MOT #3

MOT test number

MOT test number

758558065670

Result

Pass with rectification

Nearside Front Direction indicator not working (1.4.A.2c)

MOT #2		2016-12-19 09:57
MOT test	number	745255537636
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2015-12-14 14:12
MOT test number	655764706798
Result	✓ Passed

CarCheck.co.uk page 5/12



FD62EAG
report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\sim	wne	سا سن	:	
	wne	רו די	IIST	nrv

*		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full		DTA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK W	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-01-01
Last registration	2024-01-09
Complete history	See info



Registration #1	2013-01-01	27 mi
Registration #2	2015-12-14	34.790 mi
Registration #3	2016-12-19	49.595 mi
Registration #4	2017-08-24	53.027 mi
Registration #5	2017-08-24	53.027 mi
Registration #6	2018-07-31	57.634 mi
Registration #7	2019-08-23	62.947 mi
Registration #8	2020-08-21	66.816 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #13 Registration #14		11.777 ea

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1775 mm
Height	1285 mm
Length	4240 mm
Wheel base	2570 mm
Kerb weight	1275 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	FA2G857784

CarCheck.co.uk page 12/12