



AEI3YTN


report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT PLUS
Colour	Blue
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-03-29
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	18
Total items failed	29

MOT #9	2020-09-10 14:11
MOT test number	179590122477
Result	✓ Passed
Next expiry date	2021-09-09

MOT #8	2020-09-10 11:47
MOT test number	581583819075
Result	✗ Failed
Fail	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #7	2019-03-06 14:45
MOT test number	439387823162
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #6**

2019-03-06 11:15

MOT test number

742348866545

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

MOT #5

2018-02-26 12:30

MOT test number

636759054951

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4**

2018-02-26 11:27

MOT test number

367704934245

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Headlamp aim too low (1.8)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Front Valve stem seriously damaged (4.1.D.1e)
- Fail** Nearside Headlamp aim too low (1.8)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Front Valve stem seriously damaged (4.1.D.1e)

MOT #3

2017-02-24 09:21

MOT test number

101295374392

Result**✓ Passed**

- Advice** O/s/r tyre low 3mm
- Advice** Under trays fitted
- Advice** Body damage o/s/f of car

**MOT #2**

2017-02-23 10:54

MOT test number

333057303304

Result**✗ Failed**

- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)
- Advice** Body damage o/s/f of car
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Both front discs liped
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Valve stem seriously damaged (4.1.D.1e)
- Advice** O/s/r tyre low 3mm
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Exhaust system not adequately supported (7.1.1)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front Valve stem seriously damaged (4.1.D.1e)
- Advice** Under trays fitted
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1

2016-03-04 09:14

MOT test number

361078313369

Result**✓ Passed**

- Advice** Under trays fitted



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✗
MOT
Expired:
29 March 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	29 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	AE13YTN
Plate since	2019-09-28
Current registration	AE13YTN
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-03-01
Last registration	2020-09-10
Complete history	See info



Registration #1	2013-03-01	27 mi
Registration #2	2016-03-04	56.190 mi
Registration #3	2017-02-23	74.138 mi
Registration #4	2017-02-24	74.139 mi
Registration #5	2018-02-26	90.473 mi
Registration #6	2018-02-26	90.473 mi
Registration #7	2019-09-20	105.277 mi
Registration #8	2019-09-20	105.277 mi
Registration #9	2019-09-20	105.277 mi
Registration #10	2019-09-20	105.277 mi
Registration #11	2020-09-10	105.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFS0006719