



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Grey
Year of manufacture	2013
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-21
MOT pass rate	50 %
MOT passed	6
Failed MOT tests	6
Total advice items	21
Total items failed	13

MOT #12	2024-02-22 15:48
MOT test number	882139338313
Result	✓ Passed
Next expiry date	2025-02-21

MOT #11	2024-02-21 11:02
MOT test number	539897003673
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Exhaust system insecure front and rear mountings broken (6.1.2 (a))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Fail	Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Windscreen washer not working (3.5 (a))

MOT #10	2021-03-10 15:27
MOT test number	506947107409
Result	✓ Passed

**MOT #9**

2021-03-10 09:46

MOT test number

178798943219

Result**✗ Failed**

Fail Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

Fail Nearside Rear Service brake excessively fluctuating (1.2.1 (e))

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Nearside Front Service brake fluctuating, but not excessively and offside front (1.2.1 (e))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Front Brake disc significantly and obviously worn below minimum (1.1.14 (a) (i))

MOT #8

2019-09-27 09:26

MOT test number

857042617493

Result**✓ Passed**

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear wheel bearing not fully tested due to binding brake

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear wheel bearing not fully checked due to binding brake

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2019-09-27 06:56**MOT test number** 360213240180**Result** ✗ Failed

- Advice** Nearside Rear wheel bearing not fully tested due to binding brake
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear wheel bearing not fully checked due to binding brake
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2018-09-24 15:35**MOT test number** 344064625608**Result** ✓ Passed**MOT #5** 2018-09-24 12:32**MOT test number** 349918445432**Result** ✗ Failed

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4 2017-09-16 08:01**MOT test number** 314328860852**Result** ✓ Passed



MOT #3	2017-09-16 08:01
MOT test number	147362283691
Result	✗ Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)

MOT #2	2016-09-19 12:30
MOT test number	949044632531
Result	✓ Passed
Advice	Nearside Rear Tyre side walls perished

MOT #1	2016-09-19 08:51
MOT test number	317292842642
Result	✗ Failed
Fail	Exhaust system not adequately supported Center support bracket broken (7.1.1)
Advice	Nearside Rear Tyre side walls perished



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 SV63YBT
Plate since	2019-03-28
Current registration	 SV63YBT
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-30
Last registration	2024-02-22
Complete history	See info



Registration #1	2013-09-30	10 mi
Registration #2	2016-09-19	27.190 mi
Registration #3	2016-09-19	27.190 mi
Registration #4	2017-09-16	35.705 mi
Registration #5	2017-09-16	35.705 mi
Registration #6	2018-09-24	45.850 mi
Registration #7	2018-09-24	45.850 mi
Registration #8	2019-09-22	55.995 mi
Registration #9	2019-09-22	55.995 mi
Registration #10	2020-09-20	66.140 mi
Registration #11	2020-09-20	66.140 mi
Registration #12	2021-09-18	76.285 mi
Registration #13	2021-09-18	76.285 mi
Registration #14	2024-02-22	86.430 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3021550