



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | C30 SPORT |
| Colour | White |
| Year of manufacture | 2009 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 99 BHP |
| Max. torque | 150 Nm at 4.000 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.4 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 167 g/km |
| CO2 label | H |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-10 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-22 |
| MOT pass rate | 75 % |
| MOT passed | 12 |
| Failed MOT tests | 4 |
| Total advice items | 35 |
| Total items failed | 2 |

| | |
|------------------|--|
| MOT #16 | 2023-11-23 16:40 |
| MOT test number | 196106961494 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-22 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #15 | 2022-11-17 13:06 |
| MOT test number | 442625817979 |
| Result | ✓ Passed |
| Advice | Exhaust has a minor leak of exhaust gases rear box (6.1.2 (a)) |
| Advice | Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) |
| Minor | Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i)) |
| Advice | Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e)) |

**MOT #14** 2022-11-04 11:30**MOT test number** 316381077668**Result** ✗ Failed**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Unable to test offside front wheel bearing due to brake bind**MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Exhaust has a minor leak of exhaust gases rear box (6.1.2 (a))**MAJOR** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**MOT #13** 2021-10-01 14:29**MOT test number** 368639049235**Result** ✓ Passed**MOT #12** 2021-09-29 12:38**MOT test number** 355653389902**Result** ✗ Failed**MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #11** 2020-11-04 16:13**MOT test number** 606335235393**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2020-10-29 16:30**MOT test number** 588139207890**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush close to limit (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9 2019-06-06 16:00**MOT test number** 597101825684**Result** ✓ Passed**MOT #8** 2018-10-20 08:55**MOT test number** 980599074243**Result** ✓ Passed**MOT #7** 2017-10-23 09:45**MOT test number** 676845527570**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2016-10-28 09:22**MOT test number** 623733791016**Result** ✓ Passed**MOT #5** 2015-10-31 11:55**MOT test number** 843206696738**Result** ✓ Passed**MOT #4** 2014-11-03 14:19**MOT test number** 429577104450**Result** ✓ Passed**MOT #3** 2013-11-04 12:31**MOT test number** 846668903325**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-11-04 12:31**MOT test number** 157098803333**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|------------------|
| MOT #1 | 2012-11-05 10:29 |
| MOT test number | 239300912399 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
22 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 22 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YP59LRJ |
| Plate since | 2019-09-28 |
| Current registration | YP59LRJ |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2009-11-07 |
| Last registration | 2023-11-23 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-11-07 | 28 mi |
| Registration #2 | 2012-11-05 | 41.015 mi |
| Registration #3 | 2013-11-04 | 49.922 mi |
| Registration #4 | 2014-11-03 | 60.711 mi |
| Registration #5 | 2015-10-31 | 72.191 mi |
| Registration #6 | 2016-10-28 | 76.919 mi |
| Registration #7 | 2017-10-23 | 82.938 mi |
| Registration #8 | 2018-10-20 | 87.935 mi |
| Registration #9 | 2019-06-06 | 90.999 mi |
| Registration #10 | 2020-06-06 | 95.999 mi |
| Registration #11 | 2021-06-06 | 100.999 mi |
| Registration #12 | 2022-06-06 | 105.999 mi |
| Registration #13 | 2023-06-06 | 110.999 mi |
| Registration #14 | 2024-06-06 | 115.999 mi |
| Registration #15 | 2025-06-06 | 120.999 mi |
| Registration #16 | 2026-06-06 | 125.999 mi |
| Registration #17 | 2027-06-06 | 130.999 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4266 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1277 kg |
| Max. allowed weight | 1700 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |

| | |
|---------------|--------|
| Engine number | 156670 |
|---------------|--------|