



LOI2DXV

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH TDI
Colour	Black
Year of manufacture	2012
Top speed	106 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-22
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	32
Total items failed	5

MOT #8	2019-05-24 14:34
MOT test number	594723076788
Result	✓ Passed
Next expiry date	2020-12-19
Minor	Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))
Advice	Offside Rear Nail in tyre
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Tyre obviously under inflated (5.2.3 (h) (i))

**MOT #7**

2019-05-24 08:42

MOT test number

392309439482

Result**✗ Failed**

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Tyre obviously under inflated (5.2.3 (h) (i))

Advice Offside Rear Nail in tyre

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

2018-05-25 11:22

MOT test number

195553311580

Result**✓ Passed**

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside number plate light not working

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #5**

2018-05-24 14:53

MOT test number

401568743202

Result

✗ Failed

Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Offside number plate light not working

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

2017-05-22 12:03

MOT test number

764129894554

Result

✓ Passed

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #3

2016-06-20 08:14

MOT test number

466483648582

Result

✓ Passed

Advice

Car wet at time of test

**MOT #2**

2015-05-29 11:25

MOT test number

456499945113

Result

✓ Passed

- Advice** Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Front tyres wearing on edges

MOT #1

2015-05-29 09:59

MOT test number

119989645156

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Fail** Rear registration plate faded (6.3.1d)
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Front tyres wearing on edges
- Fail** Front registration plate faded (6.3.1d)
- Advice** Front Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
22 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	22 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LO12DXV
Plate since	2020-03-29
Current registration	 LO12DXV
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2012-06-14
Last registration	2019-05-24
Complete history	See info



Registration #1	2012-06-14	11 mi
Registration #2	2015-05-29	28.531 mi
Registration #3	2015-05-29	28.536 mi
Registration #4	2016-06-20	37.940 mi
Registration #5	2017-05-22	46.137 mi
Registration #6	2018-05-29	55.337 mi
Registration #7	2018-05-29	55.337 mi
Registration #8	2018-05-29	55.337 mi
Registration #9	2018-05-29	55.337 mi
Registration #10	2019-05-24	55.337 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2575 mm
Kerb weight	1134 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CFWA293647