



HYUNDAI

EFIIUOP

report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Black
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K





## MOT history

MOT expiry date	2021-07-12
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	25
Total items failed	10

MOT #21	2020-07-13 11:02
MOT test number	541690039601
Result	✓ Passed
Next expiry date	2021-07-12

MOT #20	2020-07-13 11:02
MOT test number	282466151562
Result	✗ Failed
Pass with rectification	Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Parking brake lever pivot worn to the extent that the brake may inadvertently release (1.1.6 (b) (ii))

MOT #19	2018-10-29 17:35
MOT test number	100612529008
Result	✓ Passed

MOT #18	2018-05-12 09:18
MOT test number	697172454159
Result	✓ Passed
Advice	Nearside Front Track rod end ball joint has slight play (2.2.B.1f)
Advice	Front tyres inner edge worn
Advice	Oil leak

**MOT #17** 2018-04-28 13:50**MOT test number** 659362331866**Result** ✓ Passed**MOT #16** 2018-04-28 11:21**MOT test number** 389788236545**Result** ✗ Failed

- Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #15** 2017-11-01 10:53**MOT test number** 325158234388**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin both side (3.5.1g)
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Rear Brake pad(s) wearing thin both side (3.5.1g)

**MOT #14** 2017-11-01 10:53**MOT test number** 732907540027**Result** ✗ Failed

- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Rear Brake pad(s) wearing thin both side (3.5.1g)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin both side (3.5.1g)

**MOT #13** 2017-05-01 13:08**MOT test number** 750363902995**Result** ✓ Passed**Advice** Rear Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear Direction indicators slightly discoloured both side (1.4.A.2f)**MOT #12** 2017-05-01 13:08**MOT test number** 960258576509**Result** ✗ Failed**Advice** Rear Parking brake lever has little reserve travel (3.1.6b)**Pass with rectification** Front All position lamps not working both side (1.1.A.3b)**Advice** Rear Direction indicators slightly discoloured both side (1.4.A.2f)**MOT #11** 2016-11-01 15:33**MOT test number** 827733516383**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both (1.4.A.2f)**Advice** Rear Tyre worn close to the legal limit both sides (4.1.E.1)**MOT #10** 2016-05-09 10:34**MOT test number** 551767038187**Result** ✓ Passed

**MOT #9** 2015-05-22 13:55**MOT test number** 278552645431**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2015-05-22 12:23**MOT test number** 958612945184**Result** ✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Brake hose seriously damaged (found during steering lock to lock check) (2.2.D.2b)

**MOT #7** 2014-11-22 11:33**MOT test number** 398456324365**Result** ✓ Passed**MOT #6** 2014-05-23 12:51**MOT test number** 145103244156**Result** ✓ Passed



<b>MOT #5</b>	2014-05-23 12:51
<b>MOT test number</b>	517373544182
<b>Result</b>	✗ Failed
<div><b>Pass with rectification</b> Offside Front Wheel nut(s) missing (4.2.A.1e)</div>	
<b>MOT #4</b>	2013-11-25 12:06
<b>MOT test number</b>	768259923322
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2013-05-28 11:55
<b>MOT test number</b>	479058843167
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2012-11-26 13:37
<b>MOT test number</b>	278101332346
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2012-05-28 14:18
<b>MOT test number</b>	239639242424
<b>Result</b>	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-05-27
Last registration	2020-07-13
Complete history	<a href="#">See info</a>



Registration #1	2011-05-27	28 mi
Registration #2	2012-05-28	11.618 mi
Registration #3	2012-11-26	23.174 mi
Registration #4	2013-05-28	34.379 mi
Registration #5	2013-11-25	45.535 mi
Registration #6	2014-05-23	51.560 mi
Registration #7	2014-11-22	62.826 mi
Registration #8	2015-05-22	74.230 mi
Registration #9	2015-05-22	74.231 mi
Registration #10	2016-05-09	84.087 mi
Registration #11	2016-11-01	104.714 mi
Registration #12	2016-11-01	104.714 mi
Registration #13	2016-11-01	104.714 mi
Registration #14	2016-11-01	104.714 mi
Registration #15	2016-11-01	104.714 mi
Registration #16	2016-11-01	104.714 mi
Registration #17	2016-11-01	104.714 mi
Registration #18	2016-11-01	104.714 mi
Registration #19	2016-11-01	104.714 mi
Registration #20	2016-11-01	104.714 mi
Registration #21	2016-11-01	104.714 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

<b>Number of axles</b>	2
<b>Engine number</b>	D4CBB827791