






General information

Make	AUDI
Model	A4 TFSI S LINE
Colour	Grey
Year of manufacture	2019
Top speed	140 mph
0 - 100 km/h	7.5 seconds
0 - 60 mph	8.9 seconds
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 148 BHP
Max. torque	320 Nm at 1.450 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.9 mpg
Consumption extra urban	47.0 mpg
Consumption combined	39.2 mpg
CO2 emission	135 g/km
CO2 label	E







Internet history

Entry 2	
Date	2022-05-31
Pictures	25
Listing price	<u>View report</u>



source: yesauto.com

Entry 1	
Date	2022-04-15
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-15
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #4	2024-04-16 14:29
MOT test number	975779564737
Result	✓ Passed
Next expiry date	2025-04-15
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #32023-03-21 16:18MOT test number585257195621Result< Passed</th>Advice
(i))Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords 245/40R19 (5.2.3 (d)
(ii))Advice
(iii)Offside Rear Nail in tyre 245/40R19Advice
(iiii)Offside Rear Tyre has a cut but not deep enough to reach the ply or cords 245/40R19 (5.2.3 (d) (iii))MinorWindscreen damaged but not adversely affecting driver's view (3.2 (a) (ii))





MOT #2	2023-03-21 14:01
MOT test number	682912323673
Result	🗙 Failed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)))
Fail Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cord	ds 245/40R19 (5.2.3 (d) (i))
Advice Offside Rear Nail in tyre 245/40R19	
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or co (i))	ords 245/40R19 (5.2.3 (d)

MOT #1	2022-03-03 12:24
MOT test number	459648082130
Result	✓ Passed
Advice Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	



Tax & MOT check

Tax due:	✓ MOT Expires: 15 April 2025
1 June 2024 Tax status Days left	Valid until 1 June
MOT expiry date Full MOT history	15 April 2025 See MOT history

Tax calculation

Vehicle class	48
Band	н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

In miles
7
2019-03-25
2024-04-16
See info



Registration #1	2019-03-25	27 mi
Registration #2	2022-03-03	54.737 mi
Registration #3		11.777 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1842 mm
Height	1428 mm
Length	4738 mm
Wheel base	2820 mm
Kerb weight	1435 kg
Max. allowed weight	2035 kg
Additional information	
Fuel tank capacity	54
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	DLVB033137