




report date: 2024-03-28

General information

Make	FORD
Model	KA TITANIUM
Colour	White
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	C





## Internet history

### Entry 2


Date	2023-02-10
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date	2021-08-05
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	14
Total items failed	1

<b>MOT #8</b>	2024-01-02 15:24
MOT test number	752301772350
Result	✓ Passed
Next expiry date	2025-01-25

<b>MOT #7</b>	2023-01-26 12:40
MOT test number	494929633568
Result	✓ Passed

<b>MOT #6</b>	2022-08-22 15:34
MOT test number	294427274559
Result	✓ Passed

- Advice** Offside Rear Coil spring mounting corroded but not seriously weakened axle cup (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring mounting corroded but not seriously weakened axle cup (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))



**MOT #5** 2021-08-02 14:46

**MOT test number** 964422607664

**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Exhaust has a minor leak of exhaust gases clamp on front pipe corroded away (6.1.2 (a))

**MOT #4** 2020-07-20 09:11

**MOT test number** 520345856738

**Result** ✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #3** 2019-07-15 15:31

**MOT test number** 469176754632

**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2** 2019-07-15 15:31

**MOT test number** 112772053611

**Result** ✗ Failed

- Pass with rectification** Exhaust has a major leak of exhaust gases Rear exhaust clamp missing (6.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #1</b>	2018-08-11 08:40
<b>MOT test number</b>	921359582644
<b>Result</b>	✓ Passed



## Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 February 2025

✓  
**MOT**

**Expires:**  
25 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	25 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

## Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>NU65WUP</b>
Plate since	2019-09-29
Current registration	<b>NU65WUP</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	11
<b>First mileage registration</b>	2015-11-23
<b>Last registration</b>	2024-01-02
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2015-11-23	29 mi
<b>Registration #2</b>	2018-08-11	27.018 mi
<b>Registration #3</b>	2019-07-15	29.535 mi
<b>Registration #4</b>	2019-07-15	29.535 mi
<b>Registration #5</b>	2020-07-20	38.365 mi
<b>Registration #6</b>	2021-08-02	48.245 mi
<b>Registration #7</b>	2022-01-02	55.277 mi
<b>Registration #8</b>	2022-01-02	55.277 mi
<b>Registration #9</b>	2022-01-02	55.277 mi
<b>Registration #10</b>	2022-01-02	55.277 mi
<b>Registration #11</b>	2024-01-02	55.277 mi

[More info >](#)



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg

Additional information

Fuel tank capacity	35 l
Number of axles	2
Engine number	1361424