





report date: 2024-03-29

#### General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	Blue
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

#### Entry 1

Date	2021-02-01	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

## MOT history

MOT #10	2021-03-11 15:37
MOT test number	694540867225
Result	✓ Passed
Next expiry date	2022-03-10
Advice Offside front tyre wearing on edges	
Advice Nearside front tyre wearing on edges	

MOT #9	2021-03-10 11:51
MOT test number	995904096122
Result	<b>×</b> Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside front tyre wearing on edges	
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside front tyre wearing on edges	
Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	

MOT #8	2020-01-13 09:05
MOT test number	584343849288
Result	✓ Passed
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #7	2019-01-26 10:12
MOT test number	911256375087
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6 2019-01-26 10:12

**MOT test number** 698693499049

Result X Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #5 2018-01-29 09:37

**MOT test number** 782236781031

**Result** 
✓ Passed

**MOT #4** 2017-01-26 09:23

MOT test number 968589211096

**Result** 
✓ Passed

**Advice** Keep check on tyre depths

MOT #3 2016-02-03 09:31

**MOT test number** 947536885807

**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #2** 2015-01-09 09:11

MOT test number 585669105047

Result 

Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #1 2014-01-10 10:52

**MOT test number** 328340714088

**Result** ✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
********	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	NK.
Plate since	
	More info >

CarCheck.co.uk page 8/11



VU60ULW report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-01-31
Last registration	2021-03-11
Complete history	See info



Registration #1	2011-01-31	20 mi
Registration #2	2014-01-10	26.065 mi
Registration #3	2015-01-09	37.116 mi
Registration #4	2016-02-03	45.340 mi
Registration #5	2017-01-26	64.139 mi
Registration #6	2018-01-29	75.763 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		n

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Safety ratings

NCAP rating	***
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



## Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Max. allowed weight	2430 kg

## Additional information

Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R210287355

CarCheck.co.uk page 11/11