



Mercedes-Benz

KE06CXY


report date: 2024-03-28

General information

Make	MERCEDES
Model	VITO 111 CDI EXTRA LONG TRAVELINER
Colour	Silver
Year of manufacture	2006
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	237 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-06
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-07-04
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	12
Total items failed	13

MOT #20	2022-07-05 14:49
MOT test number	666459115227
Result	✓ Passed
Next expiry date	2023-07-04
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
Advice	Rear Oil leak, but not excessive diff (drive shaft seals) both (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2022-07-04 13:28

MOT test number

174888305796

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Oil leak, but not excessive diff (drive shaft seals) both (8.4.1 (a) (i))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #18**

2022-06-16 10:39

MOT test number

582415355918

Result**✗ Failed**

- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear reflector missing (4.8.2 (a) (ii))
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Fail** Fuel pipe leaking (6.1.3 (b) (i))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Rear fog lamp does not emit a steady red light (4.5.4 (a))

MOT #17

2021-06-17 13:20

MOT test number

447479184198

Result**✓ Passed****MOT #16**

2019-07-15 08:06

MOT test number

600492500969

Result**✓ Passed****MOT #15**

2018-07-18 11:28

MOT test number

273073354705

Result**✓ Passed**



MOT #14	2017-07-13 08:09
MOT test number	620610832800
Result	✓ Passed
MOT #13	2016-07-12 10:05
MOT test number	290343773677
Result	✓ Passed
MOT #12	2015-06-30 12:04
MOT test number	575301385139
Result	✓ Passed
MOT #11	2015-06-30 12:04
MOT test number	769751385111
Result	✗ Failed
<div>Pass with rectification Nearside Stop lamp not working (1.2.1b)</div>	
MOT #10	2014-06-27 09:10
MOT test number	685078174141
Result	✓ Passed
MOT #9	2013-07-09 09:36
MOT test number	405550593118
Result	✓ Passed
MOT #8	2012-07-11 11:05
MOT test number	117263092166
Result	✓ Passed



MOT #7	2011-07-04 14:29
MOT test number	478985981104
Result	✓ Passed
MOT #6	2010-06-29 13:30
MOT test number	470560480143
Result	✓ Passed
MOT #5	2009-07-09 15:03
MOT test number	504870299190
Result	✓ Passed
MOT #4	2008-07-02 18:40
MOT test number	221844288494
Result	✓ Passed
MOT #3	2008-06-26 13:00
MOT test number	224708578487
Result	✓ Passed
MOT #2	2007-07-16 17:23
MOT test number	240887997437
Result	✓ Passed
MOT #1	2006-07-20 11:52
MOT test number	323521706421
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	KE06CXY
Plate since	2019-06-29
Current registration	KE06CXY
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-29
Last registration	2022-07-05
Complete history	See info



Registration #1	2006-03-29	7 mi
Registration #2	2006-07-20	221 mi
Registration #3	2007-07-16	8.761 mi
Registration #4	2008-06-26	17.825 mi
Registration #5	2008-07-02	18.036 mi
Registration #6	2009-07-09	28.461 mi
Registration #7	2010-06-29	36.690 mi
Registration #8	2011-07-04	47.702 mi
Registration #9	2012-07-11	59.423 mi
Registration #10	2013-07-09	72.407 mi
Registration #11	2014-06-27	83.360 mi
Registration #12	2015-06-27	95.377 mi
Registration #13	2016-06-27	107.394 mi
Registration #14	2017-06-27	119.411 mi
Registration #15	2018-06-27	131.428 mi
Registration #16	2019-06-27	143.445 mi
Registration #17	2020-06-27	155.462 mi
Registration #18	2021-06-27	167.479 mi
Registration #19	2022-06-27	179.496 mi
Registration #20	2023-06-27	191.513 mi
Registration #21	2024-03-28	203.530 mi

More info >



Dimensions & weight

Width	1906 mm
Height	1872 mm
Length	5223 mm
Kerb weight	1965 kg
Max. allowed weight	2940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	64698250203622