





report date: 2024-03-29

General information

Make	FIAT
Model	500L MULTIJET POP STAR
Colour	Silver
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2022-06-09

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-15

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-17
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	26
Total items failed	0

MOT #9	2023-07-18 19:05
MOT test number	396817604356
Result	✓ Passed
Next expiry date	2024-07-17

MOT #8	2022-06-16 14:38
MOT test number	981629371646
Result	✓ Passed
Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	

MOT #7		2022-06-15 11:39
MOT test	number	862862781958
Result		X Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively both sides ((3.4 (b) (ii))
Advice	Offside Rear Nail in tyre	
DANGER	OUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice	Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2021-09-24 10:04

MOT test number 903544612338

Result ✓ Passed

Advice Offside Rear fog lamp leans damaged

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2021-07-21 06:29

MOT test number 516851591524

Result X Failed

DANGEROUS Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Front Headlamp aim too high (4.1.2 (a))

Advice Offside Rear rear lower rear fog lamp leans damaged

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2021-06-29 08:23

MOT test number 600798002811

Result X Failed

MAJOR Nearside Front Lower Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/55/16 (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

MAJOR Offside Rear Outer Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Offside Rear Lower Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i))

MAJOR Offside Front Headlamp aim too high broken (4.1.2 (a))

MAJOR Offside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

MOT #3 2019-04-27 16:05

MOT test number 642018486290

Result
✓ Passed

MOT #2 2018-04-04 11:41

MOT test number 300229089476

Result ✓ Passed

MOT #1 2017-04-29 15:07

MOT test number 683735391652

Result \(\sqrt{Passed} \)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/12





report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



WV14YPA report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



WV14YPA report date: 2024-03-29

Owner history

· ·		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		e?

	More info	>
Plate changes See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



WV14YPA report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-18
Last registration	2023-07-18
Complete history	See info



Registration #1	2014-03-18	6 mi
Registration #2	2017-04-29	68.485 mi
Registration #3	2018-04-04	75.408 mi
Registration #4	2019-04-27	79.089 mi
Registration #5	2021-06-29	82.200 mi
Registration #6	2021-07-21	82.387 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		91,779 esi
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1365 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles2Engine number6946424