





report date: 2024-03-29

General information

Make	VOLKSWAGEN	
Model	CADDY C20 PLUS TDI STARTLINE	
Colour	White	
Year of manufacture	2017	
Top speed	107 mph	
0 - 100 km/h	17.6 seconds	
0 - 60 mph	12.0 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	55 kW / 75 HP / 101 BHP
Max. torque	225 Nm at 2.300 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/10



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-01
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #6	2023-08-02 15:18
MOT test number	674871306161
Result	✓ Passed
Next expiry date	2024-08-01

MOT #5	2023-07-27 15:51
MOT test number	841886849116
Result	X Failed
Advice Nearside Rear Brake pad(s) wearing thin worn to limit advise replacement (1.7)	1.13 (a) (ii))
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #4	2022-03-05 10:17	
MOT test number	485326141554	
Result	✓ Passed	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT #3 2022-03-05 10:17

MOT test number 299142304848

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #2 2021-03-07 15:04

MOT test number 859474885015

Result ✓ Passed

MOT #1 2020-10-06 14:38

MOT test number 946817343379

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear tyre perishing

Advice Under trays fitted

CarCheck.co.uk page 3/10



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Туре

Damage 2

Category

Type

Date



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



DX67NNP report date: 2024-03-29

Owner history

Owner History	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
See in this cheek in this volks who live had affected that is places.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 7/10



DX67NNP report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-09-27
Last registration	2023-08-02
Complete history	See info



Registration #1	2017-09-27	20 mi
Registration #2	2020-10-06	42.821 mi
Registration #3	2021-03-07	46.955 mi
Registration #4	2022-03-05	53.274 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.777 es

More info >

CarCheck.co.uk page 9/10



DX67NNP report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2065 mm
Height	1823 mm
Length	4408 mm
Wheel base	2 mm
Kerb weight	1458 kg
Max. allowed weight	2197 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 10/10

CarCheck.co.uk page 10/10

Number of seats	2
Number of axles	2
Engine number	DFSF225312