



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Black
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 3

Date	2021-12-21
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date	2021-08-31
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-08-29
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-11-27
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	24
Total items failed	23

MOT #20	2023-11-28 15:32
MOT test number	229371819716
Result	✓ Passed
Next expiry date	2024-11-27
Advice	Nearside Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2023-11-28 10:13
MOT test number	845708311614
Result	✗ Failed
Fail	Nearside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #18**

2023-11-03 16:50

**MOT test number**

174634314148

**Result****✗ Failed**

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))

**MOT #17**

2022-11-11 17:39

**MOT test number**

185673046790

**Result****✓ Passed**

- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Parking brake lever worn, but not excessively (1.1.6 (b) (i))

**MOT #16**

2022-11-11 17:39

**MOT test number**

138771438020

**Result****✗ Failed**

- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Parking brake lever worn, but not excessively (1.1.6 (b) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15** 2021-10-29 11:21**MOT test number** 618751804235**Result** ✓ Passed**MOT #14** 2021-03-02 09:11**MOT test number** 362520848581**Result** ✓ Passed**Advice** Exhaust flexi joint deteriorated**MOT #13** 2021-02-24 13:42**MOT test number** 489451671278**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Exhaust system insecure centre clamp broken (6.1.2 (a))**Advice** Exhaust flexi joint deteriorated**MOT #12** 2020-02-28 15:47**MOT test number** 315161259256**Result** ✓ Passed**Advice** Exhaust flexi & joints deteriorating

**MOT #11** 2020-02-21 14:32**MOT test number** 442515941364**Result** ✗ Failed

- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Exhaust flexi & joints deteriorating
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10** 2019-02-21 13:28**MOT test number** 974052866083**Result** ✓ Passed**MOT #9** 2017-08-18 08:56**MOT test number** 310966329069**Result** ✓ Passed**MOT #8** 2016-05-16 14:29**MOT test number** 611104821716**Result** ✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit wearing on inside edge (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit wearing on inside edge (4.1.E.1)

**MOT #7** 2015-06-13 10:26**MOT test number** 746974265154**Result** ✓ Passed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2015-06-13 10:26**MOT test number** 785004565107**Result** ✗ Failed

**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2014-06-14 11:12**MOT test number** 818025064152**Result** ✓ Passed**MOT #4** 2013-06-12 12:29**MOT test number** 915093763153**Result** ✓ Passed**MOT #3** 2013-06-11 16:53**MOT test number** 536352163145**Result** ✗ Failed

**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**MOT #2** 2012-05-28 09:30**MOT test number** 939309942150**Result** ✓ Passed

**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #1	2012-05-28 09:30
MOT test number	655519842177
Result	✗ Failed
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
27 November 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	27 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LB09OCV</b>
Plate since	2024-03-29
Current registration	 <b>LB09OCV</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-07-15
Last registration	2023-11-28
Complete history	<a href="#">See info</a>



Registration #1	2009-07-15	25 mi
Registration #2	2012-05-28	20.115 mi
Registration #3	2013-06-11	25.070 mi
Registration #4	2013-06-12	25.070 mi
Registration #5	2014-06-14	33.736 mi
Registration #6	2015-06-13	44.469 mi
Registration #7	2016-05-16	51.033 mi
Registration #8	2017-08-18	51.577 mi
Registration #9	2019-02-21	60.350 mi
Registration #10	2020-02-21	66.563 mi
Registration #11	2020-02-28	66.691 mi
Registration #12	2020-03-20	66.777 mi
Registration #13	2020-04-20	66.877 mi
Registration #14	2020-05-20	66.977 mi
Registration #15	2020-06-20	67.077 mi
Registration #16	2020-07-20	67.177 mi
Registration #17	2020-08-20	67.277 mi
Registration #18	2020-09-20	67.377 mi
Registration #19	2020-10-20	67.477 mi
Registration #20	2020-11-20	67.577 mi
Registration #21	2020-12-20	67.677 mi
Registration #22	2021-01-20	67.777 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629