





report date: 2024-03-29

General information

Make	CITROEN
Model	DS5 E-HDI AIRDREAM DSTYLE EGS
Colour	White
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history


Entry 1

Date 2021-12-14


Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

Fail

MOT expiry date	2025-03-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	19
Total items failed	6

MOT #8	2021-12-30 14:49
MOT test number	820804993957
Result	✓ Passed
Next expiry date	2022-12-29
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriou	sly weakened (1.1.14 (a) (ii))

MOT #7	2021-02-25 10:57
MOT test number	222240672926
Result	✓ Passed

Result	✓ Passed
MOT #6	2021-02-11 10:32
MOT test number	884695959630
Result	X Failed
Minor Nearside Rear Registration plate lamp inoperative in the case (4.7.1 (b) (i))	of multiple lamps or light sources
Fail Offside Front Headlamp aim too low (4.1.2 (a))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i)))
Fail Nearside Front Side repeater not working (4.4.1 (a) (ii))	

of dirt gaitor insecure (6.1.7 (g) (ii))

Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5 2020-11-25 17:20

MOT test number 639414678628

Result X Failed

Fail Nearside Front Side repeater not working in mirror (4.4.1 (a) (ii))

Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt gaitor insecure (6.1.7 (g) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2019-11-20 10:09

MOT test number 935731543592

Result
✓ Passed

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #3 2018-11-24 10:15

MOT test number 627502837406

Result ✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 4/12



MOT #2 2017-11-27 15:31

MOT test number 958186142228

Result ✓ Passed

Advice Front brake discs worn

Advice Front Tyre worn close to the legal limit both (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear brake discs corroded

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2016-11-26 11:57

MOT test number 947821623644

Result \square Passed

Advice Rear brake discs pitted and scored

Advice Engine and under covers fitted

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

about of pliates

factor scincol

See in this check if this CITROEN had different number plates.

THE STATE OF THE S

UK UK

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-11-20
Last registration	2021-12-30
Complete history	See info



Registration #1	2013-11-20	6 mi
Registration #2	2016-11-26	37.381 mi
Registration #3	2017-11-27	53.306 mi
Registration #4	2018-11-24	69.241 mi
Registration #5	2019-11-20	83.041 mi
Registration #6		m.m.
Registration #6 Registration #7		11.777 es
		11.777 ea 11.777 ea
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1508 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1430 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFT0005332

CarCheck.co.uk page 12/12