



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Green
Year of manufacture	2007
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Gas / Bi-fuel
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-17
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	28
Total items failed	6

MOT #20	2024-01-05 10:06
MOT test number	974852068894
Result	✓ Passed
Next expiry date	2025-01-17

MOT #19	2023-01-17 15:49
MOT test number	404902073377
Result	✓ Passed

MOT #18	2023-01-17 11:21
MOT test number	361880685678
Result	✗ Failed
MAJOR Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	

MOT #17	2022-01-17 13:17
MOT test number	894147523195
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #16** 2021-01-13 10:09**MOT test number** 750592421845**Result** ✓ Passed**MOT #15** 2020-01-14 14:14**MOT test number** 183894034082**Result** ✓ Passed**MOT #14** 2019-01-18 13:08**MOT test number** 344309970665**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-01-18 12:27**MOT test number** 371747364927**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Obligatory mirror does not provide a view to the rear (3.3 (c))**MOT #12** 2018-02-16 09:51**MOT test number** 853970027403**Result** ✓ Passed**Advice** O/S/R tyre inside edge worn and badly cracked**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** N/S/F tyre edges wearing thin**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2018-02-15 09:34**MOT test number** 983584714566**Result** ✗ Failed**Fail** Offside Rear Inner Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** N/S/F tyre edges wearing thin**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** O/S/R tyre inside edge worn and badly cracked**MOT #10** 2017-02-20 10:31**MOT test number** 134378106269**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2017-02-20 10:31**MOT test number** 653462458427**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2016-02-22 13:50**MOT test number** 599414422747**Result** ✓ Passed

- Advice** Offside Front seatbelt slight fraying
- Advice** Front Brake pad(s) wearing thin inners (3.5.1g)
- Advice** Windscreen delaminating nearside lower corner

MOT #7 2015-02-23 16:15**MOT test number** 219444955087**Result** ✓ Passed**MOT #6** 2015-02-23 13:26**MOT test number** 667964355032**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2014-02-21 09:45**MOT test number** 288992454089**Result** ✓ Passed

- Notice** Light fraying to drivers belt

MOT #4 2013-02-25 09:52**MOT test number** 686206653060**Result** ✓ Passed

**MOT #3** 2012-03-12 16:02**MOT test number** 409402472053**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-03-08 10:48**MOT test number** 915587661040**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-03-09 17:37**MOT test number** 304428160057**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 January 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	H
Single payment (12 months)	£ 280,00,-
Single six month payment	£ 154,00,-
Total payable by 12 monthly instalments	£ 294,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YW07KZA
Plate since	2024-03-29
Current registration	YW07KZA
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-13
Last registration	2024-01-05
Complete history	See info



Registration #1	2007-03-13	13 mi
Registration #2	2010-03-09	12.557 mi
Registration #3	2011-03-08	19.313 mi
Registration #4	2012-03-12	26.789 mi
Registration #5	2013-02-25	34.325 mi
Registration #6	2014-02-21	41.739 mi
Registration #7	2015-02-23	49.512 mi
Registration #8	2015-02-23	49.512 mi
Registration #9	2016-02-22	55.693 mi
Registration #10	2017-02-20	61.513 mi
Registration #11	2017-02-20	61.513 mi
Registration #12	2018-02-20	67.333 mi
Registration #13	2018-02-20	67.333 mi
Registration #14	2019-02-20	73.153 mi
Registration #15	2019-02-20	73.153 mi
Registration #16	2020-02-20	78.973 mi
Registration #17	2020-02-20	78.973 mi
Registration #18	2021-02-20	84.793 mi
Registration #19	2021-02-20	84.793 mi
Registration #20	2022-02-20	90.613 mi
Registration #21	2022-02-20	90.613 mi
Registration #22	2024-01-05	96.433 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1376 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	64013