




report date: 2024-03-29

General information

Make	MAZDA
Model	CX-5 SE-L NAV
Colour	Grey
Year of manufacture	2016
Top speed	129 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





## Internet history

### Entry 1

Date	2021-02-01
Pictures	7
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



MOT history

MOT expiry date	2025-04-21
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	4

**MOT #8** 2024-04-15 15:25

**MOT test number** 172545084509

**Result** ✓ Passed

**Next expiry date** 2025-04-21

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2024-04-15 11:01

**MOT test number** 352220989341

**Result** ✗ Failed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Nearside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Rear Nail in tyre

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #6** 2023-04-18 10:54

**MOT test number** 490387522253

**Result** ✓ Passed



<b>MOT #5</b>	2022-04-11 12:57
<b>MOT test number</b>	628078443837
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing 225/55R19 (5.2.3 (d) (ii))
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #4</b>	2022-04-11 09:01
<b>MOT test number</b>	419709900953
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing 225/55R19 (5.2.3 (d) (ii))
<b>Fail</b>	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Fail</b>	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Advice</b>	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Fail</b>	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

<b>MOT #3</b>	2021-04-22 12:20
<b>MOT test number</b>	631851771290
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2020-07-03 08:52
<b>MOT test number</b>	828369085645
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2019-07-25 13:54
<b>MOT test number</b>	970963701552
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 April 2025

✓  
**MOT**

**Expires:**  
21 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	21 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>DX66YJT</b>
Plate since	2024-03-29
Current registration	<b>DX66YJT</b>
Plate since	2024-03-29

More info >



**Finance check**

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.


<b>Finance company</b>	XXXXXXXX XX
<b>Date of agreement</b>	XXXXXXXX XX
<b>Agreement type</b>	XXXXXXXX XX
<b>Agreement term</b>	XXXXXXXX XX
<b>Agreement number</b>	XXXXXXXX XX
<b>Contact info</b>	XXXXXXXX XX

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	10
<b>First mileage registration</b>	2016-11-29
<b>Last registration</b>	2024-04-15
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2016-11-29	29 mi
<b>Registration #2</b>	2019-07-25	37.536 mi
<b>Registration #3</b>	2020-07-03	52.377 mi
<b>Registration #4</b>	2020-07-03	52.377 mi
<b>Registration #5</b>	2021-04-22	55.830 mi
<b>Registration #6</b>	2021-04-22	55.830 mi
<b>Registration #7</b>	2021-04-22	55.830 mi
<b>Registration #8</b>	2021-04-22	55.830 mi
<b>Registration #9</b>	2021-04-22	55.830 mi
<b>Registration #10</b>	2021-04-22	55.830 mi

**More info** >



Safety ratings

<b>NCAP rating</b>	★★★★★
<b>Adult</b>	92%
<b>Children</b>	77%
<b>Pedestrian</b>	66%
<b>Safety systems</b>	81%
<b>Overall rating</b>	83%
<b>Video</b>	<a href="#">see crash video</a>



Dimensions & weight

<b>Width</b>	1840 mm
<b>Height</b>	1450 mm
<b>Length</b>	4870 mm
<b>Wheel base</b>	2830 mm
<b>Kerb weight</b>	1330 kg
<b>Max. allowed weight</b>	1965 kg

Additional information

<b>Fuel tank capacity</b>	62 l
<b>Fuel delivery</b>	Direct Injection
<b>Number of doors</b>	4
<b>Number of seats</b>	5
<b>Number of axles</b>	2
<b>Engine number</b>	PE 20832226