



BV6100D


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Black
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-21
Pictures	54
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-20
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	19
Total items failed	2

MOT #14	2023-09-15 15:14
MOT test number	378826539092
Result	✓ Passed
Next expiry date	2024-09-20
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))

MOT #13	2023-09-15 13:56
MOT test number	466298169559
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
MAJOR	Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #12** 2022-09-21 14:35**MOT test number** 245506255107**Result** ✓ Passed**MOT #11** 2022-09-21 08:59**MOT test number** 681775264811**Result** ✗ Failed**Advice** Nearside Front brake pad wear sensor wiring broken. loom and pad side**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**DANGEROUS** Offside Rear Tyre has ply or cords exposed worn out on inside edge and has cuts/tears in worn out section (5.2.3 (d) (ii))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10** 2021-09-21 09:46**MOT test number** 228622164182**Result** ✓ Passed**MOT #9** 2021-09-21 09:45**MOT test number** 597055155042**Result** ✗ Failed**Pass with rectification** Front Brake disc significantly and obviously worn offside and nearside (1.1.14 (a) (i))**MOT #8** 2021-01-26 17:02**MOT test number** 606005452918**Result** ✓ Passed**MOT #7** 2019-07-19 12:09**MOT test number** 610273287552**Result** ✓ Passed

**MOT #6** 2019-07-19 12:09**MOT test number** 965449153729**Result** ✗ Failed**Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #5** 2018-07-17 15:11**MOT test number** 499259560009**Result** ✓ Passed**MOT #4** 2017-09-06 13:49**MOT test number** 679175825776**Result** ✓ Passed**Advice** Emissions to clean to test**Advice** Under trays fitted**MOT #3** 2016-09-08 10:38**MOT test number** 536756034036**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both side (3.5.1i)**MOT #2** 2015-09-16 09:25**MOT test number** 764154796320**Result** ✓ Passed**Advice** Emissions to clean to test**Advice** Front tyres wearing on edges**MOT #1** 2014-09-12 14:30**MOT test number** 135685254209**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
20 September 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	20 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BV61OOD
Plate since	2024-03-29
Current registration	 BV61OOD
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-16
Last registration	2023-09-15
Complete history	See info



Registration #1	2011-09-16	20 mi
Registration #2	2014-09-12	26.882 mi
Registration #3	2015-09-16	34.680 mi
Registration #4	2016-09-08	42.125 mi
Registration #5	2017-09-06	50.945 mi
Registration #6	2018-07-17	56.627 mi
Registration #7	2019-07-19	73.807 mi
Registration #8	2019-07-19	73.807 mi
Registration #9	2020-09-15	75.277 mi
Registration #10	2021-09-15	75.277 mi
Registration #11	2022-09-15	75.277 mi
Registration #12	2023-09-15	75.277 mi
Registration #13	2024-03-29	75.277 mi
Registration #14	2024-03-29	75.277 mi
Registration #15	2024-03-29	75.277 mi
Registration #16	2024-03-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAY 586764