



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER D ALL4
Colour	Brown
Year of manufacture	2011
Top speed	109 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	2.000 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-02-20
Pictures	43
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-04-03
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	20
Total items failed	6

MOT #15	2024-04-04 12:06
MOT test number	476560267072
Result	✓ Passed
Next expiry date	2025-04-03
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #14	2023-03-27 09:16
MOT test number	527783068716
Result	✓ Passed
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Front Windscreen wiper blade defective both (3.4 (b) (i))
Advice	Engine noisy on idle
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))



MOT #13	2022-03-16 12:29
MOT test number	712147756318
Result	✓ Passed
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #12	2022-03-15 12:20
MOT test number	649187894691
Result	✗ Failed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Brake performance not tested (1.2.1 (g))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #11	2021-02-26 10:13
MOT test number	569125306250
Result	✓ Passed

MOT #10	2021-02-26 10:13
MOT test number	338816965595
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9	2020-06-29 14:40
MOT test number	817135191527
Result	✓ Passed
Advice	Nearside Rear Nail in tyre

**MOT #8** 2019-06-27 15:43**MOT test number** 820447432484**Result** ✓ Passed**Minor** Offside Rear Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #7** 2019-06-27 09:27**MOT test number** 306212179418**Result** ✗ Failed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Offside Rear Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #6** 2018-06-29 11:26**MOT test number** 545919049934**Result** ✓ Passed**MOT #5** 2017-06-29 11:27**MOT test number** 558241754227**Result** ✓ Passed**MOT #4** 2016-06-27 11:13**MOT test number** 798437850553**Result** ✓ Passed**Advice** Engine cover fitted**MOT #3** 2015-06-23 16:24**MOT test number** 727624275130**Result** ✓ Passed



MOT #2	2015-06-23 10:55
MOT test number	186704975148
Result	✗ Failed
Notice	Under-trays fitted obscuring some underside components
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2014-06-24 14:27
MOT test number	335235774146
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

✓

MOT

Expires:
3 April 2025

Tax status	Expired at 1 March 2024
Days left	60 days too late
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-06-30
Last registration	2024-04-04
Complete history	See info



Registration #1	2011-06-30	19 mi
Registration #2	2014-06-24	25.386 mi
Registration #3	2015-06-23	33.657 mi
Registration #4	2015-06-23	33.666 mi
Registration #5	2016-06-27	39.941 mi
Registration #6	2017-06-29	47.431 mi
Registration #7	2018-06-29	53.745 mi
Registration #8	2019-06-27	61.019 mi
Registration #9	2019-06-27	61.019 mi
Registration #10	2020-06-27	61.019 mi
Registration #11	2020-06-27	61.019 mi
Registration #12	2020-06-27	61.019 mi
Registration #13	2020-06-27	61.019 mi
Registration #14	2020-06-27	61.019 mi
Registration #15	2020-06-27	61.019 mi
Registration #16	2020-06-27	61.019 mi
Registration #17	2020-06-27	61.019 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Kerb weight	1405 kg
Max. allowed weight	1875 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	74237850
---------------	----------