




report date: 2024-12-08

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Red
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-08-28
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	6

MOT #13 2024-08-23 09:16

MOT test number 297917331446

Result ✓ Passed

Next expiry date 2025-08-28

Advice Nearside Rear Tyre slightly damaged/cracking or perishing perished. (5.2.3 (d) (ii))

MOT #12 2024-08-22 09:28

MOT test number 175257591404

Result ✗ Failed

Fail Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure large splits inner sidewall. (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing perished. (5.2.3 (d) (ii))

Fail Offside Front Shock absorbers has negligible damping effect leaking. (5.3.2 (d))

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure large splits inner sidewall. (5.2.3 (d) (ii))

MOT #11 2023-08-29 08:11

MOT test number 241665282242

Result ✓ Passed

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Outer Track rod end ball joint has slight play and boot split. (2.1.3 (b) (i))



MOT #10	2022-08-26 14:04
MOT test number	903289217852
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2021-08-26 16:29
MOT test number	733898629281
Result	✓ Passed

MOT #8	2020-08-13 16:59
MOT test number	354449617898
Result	✓ Passed

MOT #7	2020-08-13 16:59
MOT test number	391756012309
Result	✗ Failed
Pass with rectification	Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6	2019-08-27 12:48
MOT test number	878597096153
Result	✓ Passed

MOT #5	2019-02-02 10:54
MOT test number	660979692008
Result	✓ Passed



MOT #4	2019-02-01 15:30
MOT test number	854563431100
Result	✗ Failed
Fail	Tyre tread depth below requirements of 1.6mm both front (5.2.3 (e))

MOT #3	2018-01-27 12:28
MOT test number	540843957502
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Tyre worn close to the legal limit both rear (4.1.E.1)

MOT #2	2017-01-31 09:55
MOT test number	220051957267
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2016-02-02 17:03
MOT test number	229670323912
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2025

✓
MOT

Expires:
28 August 2025

Tax status	Valid until 1 August
Days left	194
MOT expiry date	28 August 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-01-01
Current registration	XXXXXX
Plate since	2024-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-24
Last registration	2024-08-23
Complete history	See info



Registration #1	2012-09-24	16 mi
Registration #2	2016-02-02	20.434 mi
Registration #3	2017-01-31	27.239 mi
Registration #4	2018-01-27	34.571 mi
Registration #5	2019-02-01	39.850 mi
Registration #6	2019-02-02	39.850 mi
Registration #7	2019-08-27	43.325 mi
Registration #8	2020-08-13	50.238 mi
Registration #9	2021-08-27	55.277 mi
Registration #10	2022-08-27	55.277 mi
Registration #11	2023-08-27	55.277 mi
Registration #12	2024-08-23	55.277 mi
Registration #13	2024-08-23	55.277 mi
Registration #14	2024-08-23	55.277 mi
Registration #15	2024-08-23	55.277 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1802 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1516 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1220500