



E056WBN

report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX GHIA TDCI
Colour	Blue
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed CVT

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	57.6 mpg





Internet history

Entry 1	
Date	2021-11-08
Pictures	51
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #14** 2019-11-25 18:58**MOT test number** 591874137328**Result** ✓ Passed**Next expiry date** 2020-11-28**Advice** Offside Power steering component has slight seepage from a component (2.1.5 (a))**Minor** Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Under body covers fitted obstructing some areas**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement on both sides rear bushes (5.3.4 (a) (i))**MOT #13** 2019-11-25 17:04**MOT test number** 484200208954**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Under body covers fitted obstructing some areas**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Front Direction indicator incorrect colour both (4.4.3 (a))**Minor** Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement on both sides rear bushes (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Power steering component has slight seepage from a component (2.1.5 (a))

**MOT #12** 2018-11-29 11:17**MOT test number** 970535874901**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**MOT #11** 2017-11-15 16:50**MOT test number** 964541839412**Result** ✓ Passed**MOT #10** 2017-11-02 17:56**MOT test number** 274126231750**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Central Rear Statutory seat belt missing (5.1.1)**Fail** Offside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Offside Front Steering rack gaiter insecure (2.2.D.2d)**MOT #9** 2016-10-10 12:35**MOT test number** 603296433404**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #8** 2015-09-28 15:51**MOT test number** 422565695691**Result** ✓ Passed**MOT #7** 2015-09-28 15:51**MOT test number** 551691459311**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2014-10-15 15:19**MOT test number** 938718584236**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-10-22 10:06**MOT test number** 828345393229**Result** ✓ Passed**Advice** Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #4** 2012-10-24 12:37**MOT test number** 487108592257**Result** ✓ Passed**MOT #3** 2011-10-05 14:54**MOT test number** 137048371268**Result** ✓ Passed



MOT #2	2010-10-12 12:35
MOT test number	450935880220
Result	✓ Passed
MOT #1	2009-10-13 10:24
MOT test number	392616889440
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-10-04
Last registration	2019-11-25
Complete history	See info



Registration #1	2006-10-04	23 mi
Registration #2	2009-10-13	20.108 mi
Registration #3	2010-10-12	27.258 mi
Registration #4	2011-10-05	32.179 mi
Registration #5	2012-10-24	37.831 mi
Registration #6	2013-10-22	40.893 mi
Registration #7	2014-10-15	44.564 mi
Registration #8	2015-09-28	47.156 mi
Registration #9	2019-11-25	55.277 mi
Registration #10	2019-11-25	55.277 mi
Registration #11	2019-11-25	55.277 mi
Registration #12	2019-11-25	55.277 mi
Registration #13	2019-11-25	55.277 mi
Registration #14	2019-11-25	55.277 mi
Registration #15	2019-11-25	55.277 mi
Registration #16	2019-11-25	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1476 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

6B19199