



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4 8 SEATS
Colour	Silver
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	164 BHP
Max. torque	410 Nm at 2.000 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	243 g/km
CO2 label	L





## Internet history

## Entry 4

Date	2023-12-19
Pictures	8
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

## Entry 3


Date	2023-07-04
Pictures	43
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

## Entry 2

Date	2021-11-21
Pictures	9
Listing price	<a href="#">View report</a>



source: yesauto.com

## Entry 1

Date	2021-11-12
Pictures	10

Listing price

[View report](#)



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2024-08-24
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	34
Total items failed	4

MOT #21	2023-08-25 09:52
MOT test number	436458258364
Result	✓ Passed
Next expiry date	2024-08-24

MOT #20	2023-07-27 12:59
MOT test number	823711601814
Result	✗ Failed

- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Handbrake travel high but within requierments
- MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #19**

2022-07-16 08:30

**MOT test number**

559265485447

**Result**

✓ Passed

**Minor** Front Anti-roll bar ball joint dust cover severely deteriorated both sides perished (5.3.4 (b) (i))**Advice** Heavy surface corrosion to chassis, axles and all underside suspension component mounts**Advice** Rear Exhaust has a minor leak of exhaust gases silencer ar mount weld point (6.1.2 (a))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #18**

2022-07-16 08:30

**MOT test number**

763896056389

**Result**

✗ Failed

**Advice** Rear Exhaust has a minor leak of exhaust gases silencer ar mount weld point (6.1.2 (a))**Pass with rectification** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Minor** Front Anti-roll bar ball joint dust cover severely deteriorated both sides perished (5.3.4 (b) (i))**Advice** Heavy surface corrosion to chassis, axles and all underside suspension component mounts**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Pass with rectification** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**MOT #17**

2021-07-26 13:29

**MOT test number**

405785162028

**Result**

✓ Passed

**Advice** Very rusty underside**MOT #16**

2020-09-10 11:59

**MOT test number**

779222480502

**Result**

✓ Passed

**Advice** Very rusty under side

**MOT #15** 2019-09-30 13:00**MOT test number** 199945811366**Result** ✓ Passed**MOT #14** 2018-10-02 13:02**MOT test number** 606595132120**Result** ✓ Passed

- Advice** Underside components heavily corroded generally
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (ii))
- Advice** Brake hose ferrules slight corrosion
- Advice** STRONG ADVISE o/s/r tyre heavily perished / cracking
- Advice** Engine undershield excessively corroded
- Advice** STRONG ADVISE both front tyres wearing heavily on edges / treads low and tyres heavily perished and cracking

**MOT #13** 2017-10-18 07:45**MOT test number** 527213550882**Result** ✓ Passed

- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #12** 2017-05-23 07:58**MOT test number** 337207788032**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Outer Brake pipe slightly corroded both (3.6.B.2c)

**MOT #11** 2017-05-23 07:58**MOT test number** 403248590030**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Front Outer Brake pipe slightly corroded both (3.6.B.2c)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #10** 2016-05-18 14:30**MOT test number** 724603250612**Result** ✓ Passed**MOT #9** 2015-05-14 08:37**MOT test number** 367624335139**Result** ✓ Passed**MOT #8** 2014-05-30 12:00**MOT test number** 435130054159**Result** ✓ Passed**MOT #7** 2014-05-29 12:31**MOT test number** 648239244127**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #6** 2013-05-16 08:35**MOT test number** 487536433106**Result** ✓ Passed

**MOT #5** 2012-05-22 08:47**MOT test number** 236923542136**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-06-21 14:48**MOT test number** 487422471199**Result** ✓ Passed**MOT #3** 2010-06-15 08:47**MOT test number** 680386060160**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2009-06-10 11:15**MOT test number** 182401769192**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2008-06-25 09:06**MOT test number** 544607178129**Result** ✓ Passed





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-06-27
Last registration	2023-08-25
Complete history	<a href="#">See info</a>



Registration #1	2005-06-27	21 mi
Registration #2	2008-06-25	32.553 mi
Registration #3	2009-06-10	41.371 mi
Registration #4	2010-06-15	51.720 mi
Registration #5	2011-06-21	56.708 mi
Registration #6	2012-05-22	64.117 mi
Registration #7	2013-05-16	70.994 mi
Registration #8	2014-05-29	77.857 mi
Registration #9	2014-05-30	77.858 mi
Registration #10	2015-05-14	82.448 mi
Registration #11	2016-05-18	89.272 mi
Registration #12	2017-05-23	93.500 mi
Registration #13	2017-05-23	93.500 mi
Registration #14	2018-05-23	93.500 mi
Registration #15	2018-05-23	93.500 mi
Registration #16	2018-05-23	93.500 mi
Registration #17	2018-05-23	93.500 mi
Registration #18	2018-05-23	93.500 mi
Registration #19	2018-05-23	93.500 mi
Registration #20	2018-05-23	93.500 mi
Registration #21	2018-05-23	93.500 mi
Registration #22	2018-05-23	93.500 mi
Registration #23	2018-05-23	93.500 mi
Registration #24	2018-05-23	93.500 mi
Registration #25	2018-05-23	93.500 mi
Registration #26	2018-05-23	93.500 mi

**More info** >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	2190 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1KD1334867