






report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI SE
Colour	Black
Year of manufacture	2007
Top speed	125 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	285 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-01-27


Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-08-31
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	28
Total items failed	13

MOT #18		2023-08-30 12:13
MOT test	number	577400013182
Result		✓ Passed
Next expi	ry date	2024-08-31
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement o/s/n/s (5.3.4 (a) (i))		
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #17	2022-08-31 16:47
MOT test number	709174397766
Result	✓ Passed

MOT #16		2021-08-10 12:39
MOT test	number	672358657816
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Under tray fitted	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



MOT #15 2020-09-01 14:39

MOT test number 292985514218

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2020-08-26 16:01

MOT test number 369585783688

Result X Failed

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Bumper damaged and likely to cause injury when grazed or contacted front bumper (6.1.4 (a) (i))

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Service brake excessively binding x2 rear (1.2.1 (f))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Horn sound not in accordance with requirements (7.7 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Rear fog lamp not working (4.5.1 (a) (ii))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #13 2019-04-11 13:30

MOT test number 545053399205

Result \rightarrow Passed

CarCheck.co.uk page 4/14



MOT #12 2018-04-10 14:54

MOT test number 140577142133

Result ✓ Passed

Advice Offside Front Suspension arm has slight play in a pin/bush Front arm center bush (2.4.G.2)

Advice Offside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

MOT #11 2017-04-19 11:14

MOT test number 545075152161

Result Passed

Advice Nearside Front Upper Suspension arm has slight play in a pin/bush Rear arm (2.4.G.2)

Advice Offside Front Upper Suspension arm has slight play in a pin/bush Front arm (2.4.G.2)

Advice Offside Front Upper Suspension arm has slight play in a pin/bush Rear arm (2.4.G.2)

MOT #10 2017-04-18 16:17

MOT test number 152467213412

Result X Failed

Fail Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Offside Front Upper Suspension arm has slight play in a pin/bush Rear arm (2.4.G.2)

Advice Nearside Front Upper Suspension arm has slight play in a pin/bush Rear arm (2.4.G.2)

Advice Offside Front Upper Suspension arm has slight play in a pin/bush Front arm (2.4.G.2)

CarCheck.co.uk page 5/14



MOT #9 2017-04-15 09:19

MOT test number 185480534592

Result X Failed

Fail Nearside Front Upper Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)

Fail Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Rear position lamp(s) not working (1.1.A.3b)

Fail Offside Front Upper Suspension arm has excessive play in a pin/bush rear (2.4.G.2)

MOT #8 2016-04-27 15:02

MOT test number 113206753606

Result
✓ Passed

MOT #7 2016-04-27 11:35

MOT test number 121141467917

Result × Failed

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #6 2015-04-30 17:35

MOT test number 568120925189

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Advice Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Notice Engine covers fitted obscuring some components in the engine bay

MOT #5 2014-05-02 09:58

MOT test number 537952224173

CarCheck.co.uk page 6/14



MOT #4 2013-04-11 10:25

MOT test number 299381203401

Result \rightarrow Passed

MOT #3 2012-04-12 15:54

MOT test number 295493802400

Result ✓ Passed

Notice Offside rear tyre age cracking advise new

MOT #2 2011-03-12 10:14

MOT test number 768871371080

Result
✓ Passed

MOT #1 2010-05-28 15:19

MOT test number 834898440110

Result
✓ Passed


Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Both rear tyres are cracking along there tread patterns.

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners defined the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	*****
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-03
Last registration	2023-08-30
Complete history	See info



Registration #1	2007-05-03	11 mi
Registration #2	2010-05-28	22.314 mi
Registration #3	2011-03-12	27.375 mi
Registration #4	2012-04-12	36.020 mi
Registration #5	2013-04-11	40.979 mi
Registration #6	2014-05-02	46.713 mi
Registration #7	2015-04-30	51.480 mi
Registration #8	2016-04-27	56.542 mi
Registration #9	2016-04-27	56.543 mi
Registration #10	2017-04-15	61.277 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2642 mm
Kerb weight	1390 kg
Max. allowed weight	1940 kg

Additional information

		_
Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 14	/14

Number of axles 2

Engine number BRB 043790