



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	7.9 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	192 g/km
CO2 label	J





Internet history

Entry 2

Date	2021-11-10
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

Entry 1

Date	2021-11-07
Pictures	36
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-18
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	23
Total items failed	14

MOT #19	2024-03-19 17:34
MOT test number	269952883723
Result	✓ Passed
Next expiry date	2025-03-18
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Under trays fitted
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #18**

2023-11-29 19:22

**MOT test number**

160202166792

**Result****✗ Failed**

- Fail** Emissions unable to be completed (8.2.2.2 (e))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Rear Lower Suspension component pin or bush excessively worn rose bush worn (5.3.4 (a) (i))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Undertrays fitted
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #17**

2023-10-23 10:18

**MOT test number**

958424380809

**Result****✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Suspension arm ball joint excessively worn Rear arm. (5.3.4 (a) (i))
- Fail** Emissions unable to be completed CO > 4% test aborted. (8.2.1.2 (d))
- Fail** Offside Front Suspension arm ball joint excessively worn Rear arm. (5.3.4 (a) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material Both sides. (1.1.11 (c))

**MOT #16**

2022-11-16 17:24

**MOT test number**

226612274608

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush (5.3.4 (a) (i))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #15**

2022-11-15 10:40

**MOT test number**

823148661065

**Result**

✗ Failed

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush (5.3.4 (a) (i))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))

**MOT #14**

2021-11-16 13:59

**MOT test number**

414028779536

**Result**

✓ Passed

**MOT #13** 2021-11-12 14:46**MOT test number** 615553259827**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12** 2021-01-20 09:16**MOT test number** 770694313402**Result** ✓ Passed**MOT #11** 2020-02-06 15:19**MOT test number** 159993166643**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10** 2019-05-02 09:24**MOT test number** 113094580078**Result** ✓ Passed**MOT #9** 2019-05-02 09:24**MOT test number** 533163965678**Result** ✗ Failed**Pass with rectification** Headlamp aim too low (4.1.2 (a))**MOT #8** 2019-01-24 12:13**MOT test number** 772462573362**Result** ✓ Passed

**MOT #7** 2018-01-10 11:11**MOT test number** 823554241990**Result** ✓ Passed**MOT #6** 2017-01-19 09:46**MOT test number** 126375749068**Result** ✓ Passed**MOT #5** 2016-01-14 12:09**MOT test number** 608392786362**Result** ✓ Passed**MOT #4** 2016-01-14 11:31**MOT test number** 560319773003**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Pass with rectification** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2015-01-23 14:36**MOT test number** 227393225003**Result** ✓ Passed**MOT #2** 2014-01-30 11:42**MOT test number** 635100834086**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-01-10 14:02**MOT test number** 307720213090**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
18 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	18 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-






Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-10-23
Last registration	2024-03-19
Complete history	<a href="#">See info</a>



Registration #1	2009-10-23	14 mi
Registration #2	2013-01-10	31.841 mi
Registration #3	2014-01-30	43.316 mi
Registration #4	2015-01-23	51.597 mi
Registration #5	2016-01-14	66.689 mi
Registration #6	2016-01-14	66.689 mi
Registration #7	2017-01-19	73.097 mi
Registration #8	2018-01-10	80.636 mi
Registration #9	2019-01-24	89.117 mi
Registration #10	2019-05-02	90.866 mi
Registration #11	2019-05-02	90.866 mi
Registration #12	2019-05-02	90.866 mi
Registration #13	2019-05-02	90.866 mi
Registration #14	2019-05-02	90.866 mi
Registration #15	2019-05-02	90.866 mi
Registration #16	2019-05-02	90.866 mi
Registration #17	2019-05-02	90.866 mi
Registration #18	2019-05-02	90.866 mi
Registration #19	2019-05-02	90.866 mi
Registration #20	2019-05-02	90.866 mi
Registration #21	2019-05-02	90.866 mi
Registration #22	2019-05-02	90.866 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431127678