



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO ACTIVE TJET
Colour	Black
Year of manufacture	-
Top speed	132 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg



**MOT history**

MOT #15	2020-11-30 09:44
MOT test number	763113024230
Result	✓ Passed
Next expiry date	2021-12-06
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Exhaust backbox corroded.

MOT #14	2020-11-30 09:44
MOT test number	199377167558
Result	✗ Failed
Advice	Rear Exhaust backbox corroded.
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13	2019-06-07 14:15
MOT test number	313629962399
Result	✓ Passed

MOT #12	2019-06-07 10:16
MOT test number	789365409874
Result	✗ Failed
Fail	Offside Front Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))
Fail	Rear Exhaust system insecure (6.1.2 (a))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #11** 2018-05-10 14:27**MOT test number** 509712349334**Result** ✓ Passed**Advice** Coolant leak**Advice** Nearside Rear Nail in tyre unrepairable**MOT #10** 2018-05-09 08:23**MOT test number** 959670828910**Result** ✗ Failed**Advice** Coolant leak**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Nail in tyre unrepairable**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Parking brake lever has no reserve travel (3.1.6b)

**MOT #9** 2018-03-05 11:00**MOT test number** 606427692460**Result** ✗ Failed**Advice** Nearside wiper torn**Advice** Coolant level low**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake discs worn**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2017-02-02 17:14**MOT test number** 411577560565**Result** ✓ Passed**Advice** Exhaust back box outer skin corroded**MOT #7** 2017-02-02 10:56**MOT test number** 780220414714**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Exhaust back box outer skin corroded

**MOT #6** 2016-02-09 10:21**MOT test number** 976816929434**Result** ✓ Passed**Advice** Rear exhaust outer casing corroding**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)**MOT #5** 2015-02-17 11:07**MOT test number** 209848945096**Result** ✓ Passed**Notice** Rear exhaust silencer and connecting pipe corroded**Notice** Front discs corroded**MOT #4** 2014-02-18 15:21**MOT test number** 995729744004**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-02-11 17:04**MOT test number** 815222243092**Result** ✓ Passed**Notice** Nearside rear tyre perished**MOT #2** 2012-02-13 12:50**MOT test number** 645644042030**Result** ✓ Passed



MOT #1	2011-02-25 09:28
MOT test number	889716051061
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-01
Last registration	2020-11-30
Complete history	See info



Registration #1	2008-03-01	8 mi
Registration #2	2011-02-25	31.145 mi
Registration #3	2012-02-13	38.704 mi
Registration #4	2013-02-11	45.503 mi
Registration #5	2014-02-18	51.892 mi
Registration #6	2015-02-17	57.252 mi
Registration #7	2016-02-09	63.069 mi
Registration #8	2017-02-02	70.265 mi
Registration #9	2018-02-02	75.277 mi
Registration #10	2019-02-02	80.289 mi
Registration #11	2020-02-02	85.301 mi
Registration #12	2021-02-02	90.313 mi
Registration #13	2022-02-02	95.325 mi
Registration #14	2023-02-02	100.337 mi
Registration #15	2024-02-02	105.349 mi
Registration #16	2025-02-02	110.361 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1148842