





report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO MULTIJET MYLIFE
Colour	Blue
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	13.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-11-06


Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



2022-06-06 16:39

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT #9

Fail

MOT expiry date	2024-06-08
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #11	2023-06-03 08:05
MOT test number	651165622374
Result	✓ Passed
Next expiry date	2024-06-08
Advice Rear Exhaust mounting defective (6.1.2 (a))	

MOT #10	2022-06-09 16:49
MOT test number	800594379609
Result	✓ Passed

MOT test number 235476300150

Result × Failed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Offside Front Steering system excessively rough strut top bearing (2.1.1 (a))

MOT #8	2021-11-18 15:31
MOT test number	123206771108
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #7 2021-09-06 08:54

MOT test number 156515093665

Advice Offside Front slight roughness in suspension top mount on rotation

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2020-07-10 14:36

MOT test number 561032356328

Result \(\sqrt{Passed} \)

Advice Offside Front Upper suspension support bearing rough

MOT #5 2019-07-10 15:20

MOT test number 469687833806

Result ✓ Passed

MOT #4 2018-07-03 08:30

MOT test number 281741417634

Advice All tyres starting to crack in tread

MOT #3 2017-07-11 15:44

MOT test number 891368743821

Result \(\sqrt{Passed} \)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

CarCheck.co.uk page 4/11



MOT #2 2017-07-10 14:52

MOT test number 646635110806

Result

× Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively aero wiper (8.2.2)

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #1 2016-07-11 08:13

MOT test number 318530213233

Result ✓ Passed

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{r}}$	
Check it in the premium report and see an owner registrations. Download the full report i	<u>iere</u> .

	More info >
	More into /
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE UK
Flate since	110.0.0
Current registration	NIE
Plate since	mn.n.n
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-06-28
Last registration	2023-06-03
Complete history	See info



Registration #1	2013-06-28	7 mi
Registration #2	2016-07-11	23.283 mi
Registration #3	2017-07-10	26.583 mi
Registration #4	2017-07-11	26.596 mi
Registration #5	2018-07-03	29.353 mi
Registration #6	2019-07-10	32.971 mi
Registration #7	2020-07-10	35.950 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 ms
Registration #12		0.00 44
Registration #13		0.777 66

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	2755 mm
Kerb weight	1410 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number6992012