





report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI SPORT SPECIAL EDITION
Colour	Black
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/14



Internet history

Entry 1


Date 2021-06-03


Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-07-31
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	27
Total items failed	13

MOT #18		2023-07-11 10:24
MOT test	number	944483002783
Result		✓ Passed
Next expi	ry date	2024-07-31
Advice	Engine covers and under trays fitted obscuring view of testable components	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear light lens cracked	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #17		2022-08-01 11:04
MOT test	number	514197988002
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.	3 (e))
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/14



× Failed

MOT #16 2022-08-01 11:04

MOT test number 661393404600

Result X Failed

Pass with rectification Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Result

MOT #15 2021-07-07 14:38

MOT test number 379990060605

Result ✓ Passed

MOT #14 2020-10-16 14:06

MOT test number 622798373870

Result \rightarrow Passed

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #13 2020-10-16 10:41

MOT test number 672699936555

.....

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/14



Result

YP58JXB report date: 2024-03-29

★ Failed

MOT #12 2018-11-13 15:43

MOT test number 202538754246

Minor Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Lower Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Front Lower Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #11 2018-11-13 13:03

MOT test number 204193094262

Advice Offside Front Lower Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Lower Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2017-10-25 15:17

MOT test number 847520978918

Result ✓ Passed

MOT #9 2016-09-21 13:09

MOT test number 810778065486

Result ✓ Passed

CarCheck.co.uk page 5/14



Advice

YP58JXB report date: 2024-03-29

MOT #8 2016-09-20 16:06 **MOT test number** 310198714909 Result × Failed Fail Nearside rear brake binding (3.7.B.1) Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Fail Windscreen washer provides insufficient washer liquid (8.2.3) Offside Front coil spring broken (2.4.C.1a) Fail Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2015-09-28 12:23
MOT test number	944691162424
Result	✓ Passed
MOT #6	2014-09-22 14:10
MOT test number	809465364229
Result	✓ Passed
Notice Mid exhaust clamps corroded	
Notice Oil leak	

MOT #5	2013-09-30 09:47
MOT test number	258433473203
Result	✓ Passed

CarCheck.co.uk page 6/14



MOT #4

MOT test number

Result

Pass with rectification

Offside Stop lamp not working (1.2.1b)

Pass with rectification

Offside Rear position lamp(s) not working (1.1.A.3b)

MOT #3 2012-10-01 13:32 **MOT** test number 608805972298 Result ✓ Passed MOT #2 2012-10-01 08:57 348065572264 **MOT test number** Result × Failed Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2011-07-05 13:29
MOT test number	295406281180
Result	✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-22
Last registration	2023-07-11
Complete history	See info



Registration #1	2008-11-22	29 mi
Registration #2	2011-07-05	25.339 mi
Registration #3	2012-10-01	42.620 mi
Registration #4	2012-10-01	42.620 mi
Registration #5	2013-09-30	57.391 mi
Registration #6	2014-09-22	67.486 mi
Registration #7	2015-09-28	82.961 mi
Registration #8	2016-09-20	89.582 mi
Registration #9	2016-09-21	89.582 mi
Registration #10	2017-10-25	94.251 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		0.00 44

More info >

CarCheck.co.uk page 13/14



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1957 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 14/14