





report date: 2024-03-29

### General information

Make	PEUGEOT
Model	307 D TURBO HDI (110BHP)
Colour	Silver
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.3 mpg
Consumption extra urban	67.2 mpg
Consumption combined	54.3 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

### Entry 1

Date 2022-01-07

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# MOT history

MOT #17

MOT #18	2021-01-27 17:27
MOT test number	425463907659
Result	<b>✓</b> Passed
Next expiry date	2022-01-30

MOI #17	2020-01-21 14.33
MOT test number	313915273372
Result	✓ Passed

MOT #16		2019-01-16 11:31
MOT test	number	638078791782
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)

MOT #15	2018-01-27 15:49
MOT test number	670628137174
Result	<b>✓</b> Passed

MOI #14	2017-01-09 11.30
MOT test number	319421858771
Result	✓ Passed

MOT #13	2016-01-18 17:20
MOT test number	122011234149
Result	✓ Passed

MOT #12	2015-01-12 11:32
MOT test number	667972615058
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #11** 2014-01-18 14:58

**MOT test number** 605128614065

**MOT #10** 2013-01-26 10:21

**MOT test number** 375216923031

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2013-01-26 10:21

**MOT test number** 137196923461

**Result** X Failed

**Pass with rectification** Offside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Nearside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

**Pass with rectification** Offside Rear coil spring incomplete (2.4.C.1a)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2012-01-27 13:16

MOT test number 307617522074

CarCheck.co.uk page 4/12



report date: 2024-03-29

Passed

MOT #7 2011-01-28 18:10
MOT test number 388578621093

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Result

 MOT #6
 2010-01-23 15:36

 MOT test number
 300663920090

 Result
 ✓ Passed

**Advice** Rear brake disc slightly scored (3.5.1h)

**Notice** Wipers front worn

MOT #5 2009-01-26 08:42 MOT test number 984816729071

Result 

Passed

Advice Rear brake disc slightly pitted (3.5.1h)

MOT #4 2009-01-24 09:39

**MOT test number** 883204329078

**Result** X Failed

Fail Rear brake disc excessively pitted (3.5.1h)

MOT #3 2008-01-18 16:41

MOT test number 564278618087

**Advice** Rear brake disc slightly pitted (3.5.1h)

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT test number

Result

Advice Rear brake disc slightly pitted (3.5.1h)

Fail Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history	

,	
For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	
********	
***************************************	
***************************************	
***************************************	
***************************************	
************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-01-30
Last registration	2021-01-27
Complete history	See info



Registration #1	2004-01-30	26 mi
Registration #2	2007-01-24	46.363 mi
Registration #3	2008-01-18	61.387 mi
Registration #4	2008-01-18	61.387 mi
Registration #5	2009-01-24	64.791 mi
Registration #6	2009-01-26	64.798 mi
Registration #7	2010-01-23	66.616 mi
Registration #8	2011-01-28	68.311 mi
Registration #9	2012-01-27	70.129 mi
Registration #10	2013-01-26	75.946 mi
Registration #11		71.777 46
Registration #12		71.777 es
Registration #13		71.777 46
Registration #14		77,777 44
Registration #15		71.777 46
Registration #16		77,777 44
Registration #17		11.177 es
Registration #18		71.777 44
Registration #19		9.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1279 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Engine number	DYPS4008262

CarCheck.co.uk page 12/12