




report date: 2024-03-28

General information

Make	FORD
Model	FOCUS TITANIUM
Colour	Black
Year of manufacture	-
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg



**MOT history**

<b>MOT #11</b>	2021-05-18 16:02
<b>MOT test number</b>	897435166201
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-05-17
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))


<b>MOT #10</b>	2020-08-04 11:45
<b>MOT test number</b>	299332981499
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2020-08-03 14:55
<b>MOT test number</b>	480744621084
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Pass with rectification</b>	Offside Front Headlamp aim too low (4.1.2 (a))


<b>MOT #8</b>	2019-04-03 15:35
<b>MOT test number</b>	106912092693
<b>Result</b>	✓ Passed
<b>Advice</b>	Central Front Lower bumper undertray damaged

<b>MOT #7</b>	2019-04-03 11:06
<b>MOT test number</b>	927635101651
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Advice</b>	Central Front Lower bumper undertray damaged
<b>MAJOR</b>	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #6** 2018-04-05 09:42**MOT test number** 363924972364**Result** ✓ Passed**MOT #5** 2018-04-03 12:42**MOT test number** 431179956443**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2017-04-03 10:44**MOT test number** 757994577895**Result** ✓ Passed**MOT #3** 2016-03-31 14:26**MOT test number** 542099406579**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2014-04-05 13:34**MOT test number** 666865994009**Result**  Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Brake fluid level quite low
- Notice** Front tyres low tread,offside front bald inner edge,very low outer edge.nearside front tyre very low tread on edges
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Power steering fluid level low
- Notice** Front brake pads low
- Notice** Items removed from driver's view prior to test

**MOT #1** 2013-03-16 11:46**MOT test number** 169875973061**Result**  Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-03-31
Last registration	2021-05-18
Complete history	<a href="#">See info</a>



Registration #1	2010-03-31	20 mi
Registration #2	2013-03-16	47.527 mi
Registration #3	2014-04-05	51.792 mi
Registration #4	2016-03-31	60.397 mi
Registration #5	2017-04-03	68.266 mi
Registration #6	2018-04-03	75.161 mi
Registration #7	2019-05-20	82.277 mi
Registration #8	2020-05-20	89.393 mi
Registration #9	2021-05-18	96.509 mi
Registration #10	2022-05-18	103.625 mi
Registration #11	2023-05-18	110.741 mi
Registration #12	2024-03-28	117.857 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	AS14346