



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	1007 SPORT EU4
Colour	Grey
Year of manufacture	2008
Top speed	108 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	133 Nm at 3.250 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-17
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-13
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	29
Total items failed	8

MOT #15	2023-12-12 13:06
MOT test number	959586773384
Result	✓ Passed
Next expiry date	2024-12-13

MOT #14	2022-12-06 12:08
MOT test number	993953458287
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear exhaust corroded
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13	2021-12-14 15:57
MOT test number	421223217213
Result	✓ Passed
Advice	Rear silencer corroded
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2021-04-23 14:42

MOT test number

338468865458

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front wipers smearing
- Advice** Offside Rear coil spring corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))
- Advice** Rear exhaust box corroded

MOT #11

2021-04-23 09:04

MOT test number

511015539321

Result

✗ Failed

- Fail** Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 195 55 16 (5.2.3 (e))
- Fail** Emissions not tested no oil (8.2.1.2 (d))
- Advice** Rear exhaust box corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))
- Fail** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front wipers smearing
- Advice** Offside Rear coil spring corroded
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))



MOT #10 2020-03-28 10:04

MOT test number 550000078281

Result ✓ Passed

MOT #9 2019-04-13 11:43

MOT test number 108189671980

Result ✓ Passed

Advice Both front tyres scrubbing on the edges

Advice Exhaust back box shield corroded

MOT #8 2018-04-23 11:22

MOT test number 250591269049

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2017-04-20 15:57

MOT test number 384773259774

Result ✓ Passed

Advice Front reg cracked

**MOT #6** 2017-04-19 10:38**MOT test number** 972802934004**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure 195-50-16 bud (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front reg cracked**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2015-09-22 09:04**MOT test number** 449677720529**Result** ✓ Passed**MOT #4** 2014-07-16 12:55**MOT test number** 986677494154**Result** ✓ Passed**MOT #3** 2013-07-02 14:46**MOT test number** 866473383107**Result** ✓ Passed**MOT #2** 2012-07-02 12:07**MOT test number** 806974782131**Result** ✓ Passed**Notice** Front wipers slightly smearing**Advice** Steering column top bearing slightly worn (2.1.2c)



MOT #1	2011-07-06 12:21
MOT test number	449397281126
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
13 December 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-07-29
Last registration	2023-12-12
Complete history	See info



Registration #1	2008-07-29	18 mi
Registration #2	2011-07-06	16.576 mi
Registration #3	2012-07-02	21.372 mi
Registration #4	2013-07-02	25.301 mi
Registration #5	2014-07-16	29.348 mi
Registration #6	2015-09-22	32.144 mi
Registration #7	2017-04-19	43.650 mi
Registration #8	2017-04-20	43.650 mi
Registration #9	2018-04-23	52.304 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2020-05-29	55.377 mi
Registration #12	2021-05-29	55.377 mi
Registration #13	2022-05-29	55.377 mi
Registration #14	2023-05-29	55.377 mi
Registration #15	2024-05-29	55.377 mi
Registration #16	2025-05-29	55.377 mi
Registration #17	2026-05-29	55.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1662 mm
Height	1610 mm
Length	3731 mm
Wheel base	2315 mm
Kerb weight	1215 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	FE030232120