





report date: 2024-03-28

### General information

Make	MAZDA
Model	2 TS
Colour	White
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	74 BHP
Max. torque	119 Nm at 3.500 rpm
Engine capacity	1.349 сс
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date 2021-02-18

Pictures 17

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



# MOT history

MOT expiry date	2025-03-01
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	22
Total items failed	5

MOT #12	2024-02-29 14:44
MOT test number	389942950168
Result	✓ Passed
Next expiry date	2025-03-01
Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice Under vehicle slight corrosion	
Advice Front Tyre slightly damaged/cracking or perishing Both front tyres and wearing on inner edges (5.2.3 (d) (ii))	
Advice Offside Inner Sill corroded	
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice Nearside Inner Sill corroded	

MOT #11	2023-02-23 11:35
MOT test number	583148825945
Result	<b>✓</b> Passed
Advice Knock on rear suspension advise further investigation	

CarCheck.co.uk page 3/13



**MOT #10** 2022-02-10 09:42

**MOT test number** 208908586895

Advice Front Brake damaged, but the braking system is not adversely affected back plates corroded (1.1.21 (a) (i))

MOT #9 2021-02-09 09:19

**MOT test number** 763674452006

Result \rightarrow Passed

MOT #8 2021-02-09 09:19

**MOT test number** 161976296968

Result X Failed

**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #7 2020-02-12 15:12

MOT test number 972921383817

Result 

Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #6 2020-02-12 10:18

MOT test number 648702979974

**Result** ★ Failed

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Headlamp aim too high (4.1.2 (a))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

CarCheck.co.uk page 4/13



MOT #5

MOT test number

Result

Advice Both front tyres slightly worn edges

2019-02-14 11:33

974108763450

✓ Passed

MOT #4 2019-02-14 08:05 **MOT** test number 719421636353 Result × Failed Fail Offside Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Fail Nearside Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Offside Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail **Advice** Both front tyres slightly worn edges

**MOT** #3 2018-02-26 08:01 886029591626 **MOT** test number Result ✓ Passed **MOT** #2 2017-02-23 08:09 **MOT** test number 137121916090 Result Passed **Advice** Both rear tyres deteriorating and approaching tread limit **Advice** Nearside front tyre slight sidewall damage

CarCheck.co.uk page 5/13



MOT test number

Result

Advice Slight oil leak on engine

Advice Both front tyres worn inner edges

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SIK
Plate since	
	Moro info

CarCheck.co.uk page 10/13



#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-01
Last registration	2024-02-29
Complete history	See info



Registration #1	2013-03-01	19 mi
Registration #2	2016-02-17	19.784 mi
Registration #3	2017-02-23	29.816 mi
Registration #4	2018-02-26	40.238 mi
Registration #5	2019-02-14	50.274 mi
Registration #6	2019-02-14	50.274 mi
Registration #7	2020-02-12	59.926 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1030 kg
Max. allowed weight	1485 kg

## Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZJ B20946

CarCheck.co.uk page 13/13