



report date: 2024-03-29

General information

Make	MAZDA
Model	3 MPS
Colour	Red
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	247 BHP
Max. torque	380 Nm at 3.000 rpm
Engine capacity	2.261 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.9 mpg
Consumption extra urban	33.2 mpg
Consumption combined	29.1 mpg
CO2 emission	224 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-08
Pictures	47
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-05-13
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	17
Total items failed	4

## MOT #14 2023-04-25 12:29

MOT test number 760612650238

Result ✓ Passed

Next expiry date 2024-05-13

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D BUSHES (5.3.4 (a) (i))

**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement D BUSHES (5.3.4 (a) (i))

## MOT #13 2023-04-24 11:07

MOT test number 109915785119

Result ✗ Failed

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D BUSHES (5.3.4 (a) (i))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement D BUSHES (5.3.4 (a) (i))

## MOT #12 2022-05-09 07:57

MOT test number 822751227851

Result ✓ Passed

**MOT #11** 2021-05-14 12:20**MOT test number** 620995908451**Result** ✓ Passed**MOT #10** 2021-01-20 09:58**MOT test number** 906169039733**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))**MOT #9** 2020-01-16 09:54**MOT test number** 921596945086**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Slightly pitted on inner face/s (1.1.14 (a) (ii))**MOT #8** 2019-01-17 10:13**MOT test number** 147492173639**Result** ✓ Passed**MOT #7** 2019-01-17 09:41**MOT test number** 846117635784**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



<b>MOT #6</b>	2018-01-16 14:47
---------------	------------------

<b>MOT test number</b>	105760384345
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2017-01-28 12:26
---------------	------------------

<b>MOT test number</b>	526904785446
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2016-06-23 08:30
---------------	------------------

<b>MOT test number</b>	282035435851
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear tyre sidewall cut
---------------	---------------------------------

<b>MOT #3</b>	2015-06-29 10:38
---------------	------------------

<b>MOT test number</b>	956850385199
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-06-10 16:19
---------------	------------------

<b>MOT test number</b>	978051064136
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Engine covers fitted obscuring some components in the engine bay
---------------	--

<b>Notice</b>	Under-trays fitted obscuring some underside components
---------------	--



MOT #1	2013-06-14 17:21
MOT test number	108675663158
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
13 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	13 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-30
Last registration	2023-04-25
Complete history	<a href="#">See info</a>



Registration #1	2010-06-30	6 mi
Registration #2	2013-06-14	14.600 mi
Registration #3	2014-06-10	23.785 mi
Registration #4	2015-06-29	34.068 mi
Registration #5	2016-06-23	45.371 mi
Registration #6	2017-01-28	53.366 mi
Registration #7	2018-01-16	61.334 mi
Registration #8	2019-01-17	72.842 mi
Registration #9	2020-05-20	85.277 mi
Registration #10	2021-05-20	95.277 mi
Registration #11	2022-05-20	105.277 mi
Registration #12	2023-05-20	115.277 mi
Registration #13	2024-05-20	125.277 mi
Registration #14	2025-05-20	135.277 mi
Registration #15	2026-05-20	145.277 mi
Registration #16	2027-05-20	155.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1465 mm
Length	4435 mm
Wheel base	2640 mm
Kerb weight	1405 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L3 20393953