



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK280 AVANTGARDE
Colour	Silver
Year of manufacture	2007
Top speed	154 mph
0 - 60 mph	7.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.997 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.9 mpg
Consumption extra urban	39.2 mpg
Consumption combined	29.7 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-05
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-10
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	38
Total items failed	12

MOT #17	2023-08-11 12:31
MOT test number	771204619078
Result	✓ Passed
Next expiry date	2024-08-10
Minor	Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D Bushes (5.3.4 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front (5.3.4 (a) (i))

**MOT #16**

2023-08-09 12:31

**MOT test number**

578678585278

**Result****✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D Bushes (5.3.4 (a) (i))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn Front (5.3.4 (a) (i))
- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front (5.3.4 (a) (i))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear (5.3.4 (a) (i))

**MOT #15**

2022-08-04 09:18

**MOT test number**

226580401972

**Result****✓ Passed**

- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #14** 2021-08-10 12:12**MOT test number** 828499305716**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-10-14 11:12**MOT test number** 620536576020**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**MOT #12** 2019-10-01 13:34**MOT test number** 162719801258**Result** ✓ Passed

**MOT #11**

2019-09-17 10:40

**MOT test number**

605423655136

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #10**

2018-08-29 15:38

**MOT test number**

960356897861

**Result****✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2018-08-29 12:17

**MOT test number**

142253550706

**Result****✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Front Registration plate inscription illegible (0.1 (b))

**MOT #8** 2017-08-18 10:40**MOT test number** 435405094783**Result** ✓ Passed**MOT #7** 2016-08-16 09:30**MOT test number** 173587291812**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear tyre inner edge worn**Advice** Front b/pads getting low**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Both front tyres wearing inner edges**Advice** Rear b/pads getting low**MOT #6** 2015-03-17 15:21**MOT test number** 669136575002**Result** ✓ Passed**MOT #5** 2014-02-11 11:50**MOT test number** 236432944036**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Wiper blades worn**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #4	2013-01-28 15:15
MOT test number	158018823019
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #3	2012-01-30 16:02
MOT test number	388130832019
Result	✓ Passed

MOT #2	2011-02-07 15:50
MOT test number	889918031058
Result	✓ Passed

MOT #1	2010-02-22 14:29
MOT test number	551943850000
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
10 August 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	10 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>GU07RTV</b>
Plate since	2019-06-29
Current registration	 <b>GU07RTV</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-19
Last registration	2023-08-11
Complete history	<a href="#">See info</a>



Registration #1	2007-03-19	9 mi
Registration #2	2010-02-22	28.829 mi
Registration #3	2011-02-07	37.635 mi
Registration #4	2012-01-30	46.946 mi
Registration #5	2013-01-28	55.116 mi
Registration #6	2014-02-11	62.492 mi
Registration #7	2015-03-17	66.959 mi
Registration #8	2016-08-16	78.040 mi
Registration #9	2017-08-18	83.175 mi
Registration #10	2018-08-29	87.985 mi
Registration #11	2019-05-20	91.377 mi
Registration #12	2020-05-20	95.377 mi
Registration #13	2021-05-20	99.377 mi
Registration #14	2022-05-20	103.377 mi
Registration #15	2023-05-20	107.377 mi
Registration #16	2024-05-20	111.377 mi
Registration #17	2025-05-20	115.377 mi
Registration #18	2026-05-20	119.377 mi
Registration #19	2027-05-20	123.377 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1580 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030540240