





report date: 2024-03-28

General information

| Make | FIAT |
|---------------------|-----------------------|
| Model | DOBLO 16V SX MULTIJET |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 98 mph |
| 0 - 60 mph | 5.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 90 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 1.750 rpm |
| Engine capacity | 1.248 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 57.6 mpg |
| CO2 emission | 126 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-04

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-09-28 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 1 |

| MOT #7 | 2023-09-19 09:46 |
|--|------------------|
| MOT test number | 302307882463 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-28 |
| Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i)) | |

| MOT #6 | 2022-09-28 15:42 |
|--|------------------|
| MOT test number | 841418764029 |
| Result | ✓ Passed |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (| (a) (ii)) |

| MOT #5 | 2022-09-28 10:09 |
|---|------------------|
| MOT test number | 395638536734 |
| Result | × Failed |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a | a) (ii)) |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT #4

MOT test number

Result

MOT #3

MOT test number

MOT test number

465154615014

Result

Advice

Offside Front tyre is perishing slightly on the outer side wall

MOT test number

Result

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Engine covers & under trays fitted

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

| MOT #1 | 2018-09-05 12:52 |
|---|------------------|
| MOT test number | 360502181536 |
| Result | ✓ Passed |
| Advice Nearside Front tyre has 2 nails in the tread | |

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report | | e? |
|---|--------------------|----|
| | | |
| | | |
| | | |
| *************************************** | | |
| | | |
| | | |
| | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this FIAT had different number plates. | | |
| Number of plates | | |
| Current registration | OK SIES SIES | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | |

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-09-29 |
| Last registration | 2023-09-19 |
| Complete history | See info |



| Registration #1 | 2015-09-29 | 22 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-09-05 | 7.843 mi |
| Registration #3 | 2019-09-23 | 11.209 mi |
| Registration #4 | 2020-09-02 | 13.563 mi |
| Registration #5 | 2021-09-02 | 15.084 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1832 mm |
|---------------------|---------|
| Height | 1845 mm |
| Length | 4390 mm |
| Kerb weight | 1345 kg |
| Max. allowed weight | 2355 kg |

Additional information

| Fuel tank capacity | 60 I |
|---------------------------------|--------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 2 |
| Engine number Carcheck.co.uk | 5656639 page 10/10 |