



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO GTI
Colour	Black
Year of manufacture	2016
Top speed	147 mph
0 - 100 km/h	6.7 seconds
0 - 60 mph	6.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 kW / 192 HP / 189 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2


Date	2023-02-14
Pictures	10
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-14
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	10
Total items failed	1

MOT #8	2024-04-15 06:49
MOT test number	469020694147
Result	✓ Passed
Next expiry date	2025-04-14

MOT #7	2024-04-15 06:49
MOT test number	338654818877
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front Tyre pressure monitoring system malfunctioning or obviously inoperative TP ADJUSTED (5.2.3 (h))	

MOT #6	2023-03-02 14:55
MOT test number	636717351638
Result	✓ Passed
<div>Advice</div> Brake disc worn, pitted or scored, but not seriously weakened Front & Rear (1.1.14 (a) (ii))	
<div>Advice</div> Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

**MOT #5** 2023-03-01 13:19**MOT test number** 187382381403**Result** ✗ Failed**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Front & Rear (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #4** 2022-02-23 13:40**MOT test number** 958028495185**Result** ✓ Passed**MOT #3** 2022-02-22 12:11**MOT test number** 764712604911**Result** ✗ Failed**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**MOT #2** 2021-03-05 08:48**MOT test number** 814985026865**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2019-09-20 13:21**MOT test number** 477683972982**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 April 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	14 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>GU66GUJ</b>
Plate since	2019-06-29
Current registration	<b>GU66GUJ</b>
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-17
Last registration	2024-04-15
Complete history	<a href="#">See info</a>



Registration #1	2016-09-17	10 mi
Registration #2	2019-09-20	17.252 mi
Registration #3	2019-09-20	20.277 mi
Registration #4	2021-03-05	24.031 mi
Registration #5	2022-02-22	30.029 mi
Registration #6	2022-02-23	30.029 mi
Registration #7	2019-09-20	20.277 mi
Registration #8	2019-09-20	20.277 mi
Registration #9	2019-09-20	20.277 mi
Registration #10	2019-09-20	20.277 mi
Registration #11	2019-09-20	20.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1172 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

Number of axles	2
Engine number	DAJA014876