



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Silver
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-14
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-07
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	41
Total items failed	1

MOT #14	2023-11-08 13:27
---------	------------------

MOT test number	599851958508
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-11-07
------------------	------------

Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front Sound deadening material not fully secure under bonnet (8.1.1 (b) (i))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13**

2022-10-31 13:12

**MOT test number**

325048988467

**Result**

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside stone chip to windscreen
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Front Sound deadening material not fully secure under bonnet (8.1.1 (b) (i))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2021-11-02 12:00

**MOT test number**

899009644142

**Result**

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2021-11-02 09:50**MOT test number** 379290925369**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre is in a very poor condition (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2020-10-19 07:59**MOT test number** 869288939567**Result** ✓ Passed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2019-10-31 09:23**MOT test number** 860200329202**Result** ✓ Passed**MOT #8** 2018-10-29 09:09**MOT test number** 886805474596**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2017-11-01 10:57**MOT test number** 505317478824**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-10-19 16:55**MOT test number** 620726795486**Result** ✓ Passed**Advice** Power steering pump noisy**MOT #5** 2016-10-19 08:30**MOT test number** 820726103243**Result** ✗ Failed**Advice** Power steering fluid level low, but not below minimum (2.3.1)**Advice** Power steering pump noisy**Fail** Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**MOT #4** 2015-11-05 12:42**MOT test number** 166132178232**Result** ✓ Passed**MOT #3** 2014-11-04 11:50**MOT test number** 607378304389**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2013-11-06 09:02
MOT test number	918570913313
Result	✓ Passed

MOT #1	2012-11-01 09:52
MOT test number	426446802321
Result	✓ Passed

**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
7 November 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	7 November 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>EJ59WYL</b>
Plate since	2024-03-28
Current registration	<b>EJ59WYL</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-10
Last registration	2023-11-08
Complete history	<a href="#">See info</a>



Registration #1	2009-12-10	13 mi
Registration #2	2012-11-01	44.809 mi
Registration #3	2013-11-06	57.960 mi
Registration #4	2014-11-04	65.510 mi
Registration #5	2015-11-05	71.447 mi
Registration #6	2016-10-19	76.076 mi
Registration #7	2016-10-19	76.076 mi
Registration #8	2017-11-01	81.251 mi
Registration #9	2018-11-01	86.426 mi
Registration #10	2019-11-01	91.601 mi
Registration #11	2020-11-01	96.776 mi
Registration #12	2021-11-01	101.951 mi
Registration #13	2022-11-01	107.126 mi
Registration #14	2023-11-01	112.301 mi
Registration #15	2023-11-01	112.301 mi
Registration #16	2023-11-08	112.301 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

9C62374