



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX TITANIUM
Colour	Black
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	9.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J





## Internet history

### Entry 1

Date	2021-05-28
Pictures	15
Listing price	<a href="#">View report</a>

With the outbreak of COVID-19 and the restrictions that are being put in place to prevent the spread of infection within public venues, and the wishes of some people wanting to implement social distancing, the team at Lakeview Cars just wanted to reassure you that we have implemented measures, in order to continue with offering you our unrivaled customer service.



**AA**  
You're in  
safe hands  
This dealer has signed  
our Dealer Promise



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-30
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	51
Total items failed	12

MOT #19	2024-01-30 13:06
MOT test number	952479397311
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Offside Front Upper top mount noisy

MOT #18	2024-01-27 12:04
MOT test number	286708799631
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Offside Front Upper top mount noisy
Fail	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #17	2023-01-12 17:01
MOT test number	206133546802
Result	✓ Passed

MOT #16	2022-01-31 16:32
MOT test number	494770716988
Result	✓ Passed

**MOT #15** 2021-04-27 14:29**MOT test number** 491220590387**Result** ✓ Passed**MOT #14** 2020-07-24 15:14**MOT test number** 219682008721**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #13** 2020-07-23 17:07**MOT test number** 584683756556**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm likely to fail (5.3.3 (b) (ii))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2019-06-22 08:51

**MOT test number**

518232655654

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Anti-roll bar ball joint has slight play drop link (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play drop link (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Advise front exhaust flex slightly worn.

**MOT #11**

2019-06-22 08:51

**MOT test number**

631316604866

**Result**

✗ Failed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play drop link (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Advise front exhaust flex slightly worn.
- Advice** Offside Rear Anti-roll bar ball joint has slight play drop link (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10**

2018-06-19 09:49

**MOT test number**

946484580411

**Result**

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Advise offside front inner cv boot split.
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #9**

2018-06-19 09:49

**MOT test number**

241163120536

**Result**

✗ Failed

- Pass with rectification** Nearside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Advise offside front inner cv boot split.
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #8**

2017-06-27 09:11

**MOT test number**

684406759234

**Result**

✓ Passed

- Advice** Offside Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #7** 2016-06-25 09:33**MOT test number** 273284420192**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2015-06-22 13:09**MOT test number** 315713775148**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2015-06-20 10:53**MOT test number** 948631675142**Result** ✗ Failed**Fail** Steering rack gaiter insecure (2.2.D.2d)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-06-24 12:19**MOT test number** 625495574139**Result** ✓ Passed

**MOT #3** 2013-06-26 11:32**MOT test number** 437817073156**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2012-02-14 14:04**MOT test number** 417455142010**Result** ✓ Passed**Notice** Nearside sill section damaged**MOT #1** 2012-02-13 15:13**MOT test number** 855114042004**Result** ✗ Failed**Notice** Nearside sill section damaged**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
30 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	30 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>DU09CZG</b>
Plate since	2019-03-28
Current registration	<b>DU09CZG</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-30
Last registration	2024-01-30
Complete history	<a href="#">See info</a>



Registration #1	2009-03-30	24 mi
Registration #2	2012-02-13	8.103 mi
Registration #3	2012-02-14	8.113 mi
Registration #4	2013-06-26	16.841 mi
Registration #5	2014-06-24	25.654 mi
Registration #6	2015-06-20	34.349 mi
Registration #7	2015-06-22	34.349 mi
Registration #8	2016-06-25	43.141 mi
Registration #9	2017-06-27	51.567 mi
Registration #10	2018-06-19	59.768 mi
Registration #11	2018-06-19	59.768 mi
Registration #12	2019-06-20	68.569 mi
Registration #13	2019-06-20	68.569 mi
Registration #14	2020-06-21	77.370 mi
Registration #15	2020-06-21	77.370 mi
Registration #16	2021-06-22	86.171 mi
Registration #17	2021-06-22	86.171 mi
Registration #18	2022-06-23	94.972 mi
Registration #19	2022-06-23	94.972 mi
Registration #20	2023-06-24	103.773 mi
Registration #21	2024-01-30	112.574 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1326 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	9B33524