






report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD HARD TOP
Colour	Black
Year of manufacture	2012
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	22.6 mpg
Consumption extra urban	32.8 mpg
Consumption combined	28.3 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2022-01-08

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2022-01-07
Pictures	26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-23
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	16
Total items failed	7

MOT #13	2023-08-24 15:19
MOT test number	941719800942
Result	✓ Passed
Next expiry date	2024-08-23
Advice Both sides front wheel hub swivels damp	

MOT #12	2022-08-22 13:37
MOT test number	335569260498
Result	✓ Passed

MOT #11		2021-11-11 12:24
MOT test	number	321653459949
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1	L.1.14 (a) (ii))

MOT #10	2020-10-27 15:57
MOT test number	951367018660
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #9 2020-02-12 11:22

MOT test number 681624380613

Advice Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))

Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #8 2019-02-28 14:08

MOT test number 490634597003

Result \(\sqrt{Passed} \)

Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #7 2019-02-28 14:08

MOT test number 610851744268

Result X Failed

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #6 2018-01-19 14:35

MOT test number 148195091066

Result

Passed

Advice Power steering pipe(s) or hose(s) slightly corroded (2.3.2)

Advice Brake disc worn, pitted or scored, but not seriously weakened both rear inner swept area (3.5.1i)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 4/12



MOT #5 2018-01-19 11:22

MOT test number 623999396736

Result X Failed

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Pass with rectification Nearside Front Headlamp not working on dipped beam (1.7.5a)

Fail Brake pipe excessively corroded main front to rear (3.6.B.2c)

Advice Brake disc worn, pitted or scored, but not seriously weakened both rear inner swept area (3.5.1i)

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Power steering pipe(s) or hose(s) slightly corroded (2.3.2)

MOT #4 2017-01-19 14:39

MOT test number 680954798501

Result Passed

Advice Offside Rear Brake pipe slightly corroded front to rear at chassis leg (3.6.B.2c)

MOT #3 2016-01-15 14:34

MOT test number 743563779304

Result ✓ Passed

MOT #2 2016-01-15 12:12

MOT test number 738336003685

Result X Failed

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #1 2015-01-26 12:27

MOT test number 339926325080

Result ✓ Passed

CarCheck.co.uk page 5/12



215

Tax & MOT check

Days left



MOT expiry date 23 August 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



PY61JFE

report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-01-31
Last registration	2023-08-24
Complete history	See info



Registration #1	2012-01-31	6 mi
Registration #2	2015-01-26	11.660 mi
Registration #3	2016-01-15	17.111 mi
Registration #4	2016-01-15	17.111 mi
Registration #5	2017-01-19	25.319 mi
Registration #6	2018-01-19	37.168 mi
Registration #7	2018-01-19	37.185 mi
Registration #8	2019-02-28	51.243 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		11.777 ms

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Dimensions & weight

Width	1790 mm
Height	2128 mm
Length	4040 mm
Kerb weight	1759 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	110819213342244DT

CarCheck.co.uk page 12/12