



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | C30 R-DESIGN |
| Colour | White |
| Year of manufacture | 2010 |
| Top speed | 130 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 145 BHP |
| Max. torque | 185 Nm at 4.500 rpm |
| Engine capacity | 1.999 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 27.7 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 38.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-18 |
| Pictures | 21 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-07 |
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 21 |
| Total items failed | 7 |

| | |
|------------------|-----------------------------------------------------------------------------------------------------------------|
| MOT #15 | 2023-08-22 13:35 |
| MOT test number | 488382765456 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-07 |
| Minor | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #14 | 2022-08-15 14:08 |
| MOT test number | 308138508220 |
| Result | ✓ Passed |

| | |
|-----------------|-----------------------------------------------------------------------------------------------------------------|
| MOT #13 | 2022-08-15 09:12 |
| MOT test number | 408458960138 |
| Result | ✗ Failed |
| Fail | Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Minor | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Offside Front Nail in tyre |
| Fail | Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Fail | Nearside Front Position lamp not working x2 (4.2.1 (a) (ii)) |

**MOT #12** 2021-09-08 13:59**MOT test number** 339483544504**Result** ✓ Passed**Advice** Brake pad(s) wearing thin front & rear brake pads worn low (1.1.13 (a) (ii))**Advice** Engine oil level low**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**MOT #11** 2020-02-25 13:23**MOT test number** 699227491652**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**MOT #10** 2020-02-18 11:32**MOT test number** 365914169565**Result** ✗ Failed**Advice** Both the front and offside rear tyres have low tread on the inner edges**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**MOT #9** 2019-02-12 12:15**MOT test number** 884535527746**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-02-22 11:23**MOT test number** 105398440248**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2017-02-24 14:30**MOT test number** 204705568175**Result** ✓ Passed**MOT #6** 2016-06-15 14:47**MOT test number** 742898797661**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2016-06-15 14:00**MOT test number** 878339115977**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Front registration plate missing (6.3.1a)**MOT #4** 2015-03-06 14:55**MOT test number** 215195565083**Result** ✓ Passed**MOT #3** 2014-03-15 09:39**MOT test number** 826714174022**Result** ✓ Passed



| | |
|-----------------|----------------------------------------------------------------------|
| MOT #2 | 2014-03-13 14:53 |
| MOT test number | 349132774088 |
| Result | ✗ Failed |
| Fail | Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
| Fail | Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|------------------------------------------------------------|
| MOT #1 | 2013-03-05 10:28 |
| MOT test number | 416424063048 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
7 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 248 |
| MOT expiry date | 7 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | HY10SXX |
| Plate since | 2019-09-28 |
| Current registration | HY10SXX |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2010-03-15 |
| Last registration | 2023-08-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-03-15 | 26 mi |
| Registration #2 | 2013-03-05 | 17.024 mi |
| Registration #3 | 2014-03-13 | 23.551 mi |
| Registration #4 | 2014-03-15 | 23.560 mi |
| Registration #5 | 2015-03-06 | 27.982 mi |
| Registration #6 | 2016-06-15 | 31.122 mi |
| Registration #7 | 2016-06-15 | 31.122 mi |
| Registration #8 | 2017-02-24 | 35.299 mi |
| Registration #9 | 2018-02-22 | 39.077 mi |
| Registration #10 | 2019-03-22 | 43.255 mi |
| Registration #11 | 2019-03-22 | 43.255 mi |
| Registration #12 | 2019-03-22 | 43.255 mi |
| Registration #13 | 2019-03-22 | 43.255 mi |
| Registration #14 | 2019-03-22 | 43.255 mi |
| Registration #15 | 2019-03-22 | 43.255 mi |
| Registration #16 | 2019-03-22 | 43.255 mi |
| Registration #17 | 2019-03-22 | 43.255 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4252 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1346 kg |
| Max. allowed weight | 1750 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| | |
|------------------------|--------|
| Number of axles | 2 |
| Engine number | 186524 |