



report date: 2024-03-29

General information

Make	BMW
Model	525 525D M SPORT
Colour	Grey
Year of manufacture	2008
Top speed	146 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	400 Nm at 1.300 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-23
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-04-19
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	29
Total items failed	11

MOT #20	2024-04-20 08:47
MOT test number	203384904803
Result	✓ Passed
Next expiry date	2025-04-19
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #19	2023-02-24 11:43
MOT test number	762671265363
Result	✓ Passed
Minor	Offside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))
Minor	Nearside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))

MOT #18	2023-02-23 10:03
MOT test number	232418419752
Result	✗ Failed
Fail	Windscreen washer not working (3.5 (a))
Minor	Nearside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))
Fail	Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Minor	Offside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))

**MOT #17**

2022-03-04 14:58

**MOT test number**

921623497515

**Result**

✓ Passed

**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**MOT #16**

2022-03-04 11:37

**MOT test number**

644567988751

**Result**

✗ Failed

**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15**

2021-03-03 11:01

**MOT test number**

418142801069

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm remaining (5.2.3 (e))**MOT #14**

2021-03-03 11:01

**MOT test number**

457207615607

**Result**

✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm remaining (5.2.3 (e))**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm CORDS EXPOSED (5.2.3 (e))

**MOT #13** 2020-03-02 16:35**MOT test number** 145050732388**Result** ✓ Passed**Advice** Tested in wet condition**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12** 2020-02-29 11:17**MOT test number** 502395912921**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Windscreen damaged and affecting the driver's view of an obligatory external mirror (3.2 (a) (ii))**Advice** Tested in wet condition**MOT #11** 2019-03-04 09:37**MOT test number** 249196901993**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #10** 2019-03-01 12:05**MOT test number** 537272811154**Result** ✗ Failed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #9** 2018-03-03 16:44**MOT test number** 198914813079**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-01-19 17:58**MOT test number** 664195667376**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-01-19 17:08**MOT test number** 580139857080**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Side repeater not working (1.4.A.2c)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2015-11-23 14:08**MOT test number** 235370768177**Result** ✓ Passed

**MOT #5** 2014-11-29 09:51**MOT test number** 289363734331**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-11-30 10:20**MOT test number** 828694433333**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-12-01 09:48**MOT test number** 445316532467**Result** ✓ Passed**MOT #2** 2011-11-04 15:54**MOT test number** 985448601362**Result** ✓ Passed**MOT #1** 2011-10-14 16:32**MOT test number** 408457581284**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
19 April 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	19 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history


Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	<b>OV58EUK</b>
Plate since	2019-03-29
Current registration	<b>OV58EUK</b>
Plate since	2019-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-10-17
Last registration	2024-04-20
Complete history	<a href="#">See info</a>



Registration #1	2008-10-17	19 mi
Registration #2	2011-10-14	13.083 mi
Registration #3	2011-11-04	13.115 mi
Registration #4	2012-12-01	32.611 mi
Registration #5	2013-11-30	45.834 mi
Registration #6	2014-11-29	55.042 mi
Registration #7	2015-11-23	63.670 mi
Registration #8	2017-01-19	70.310 mi
Registration #9	2017-01-19	70.310 mi
Registration #10	2018-03-03	83.750 mi
Registration #11	2019-03-01	81.921 mi
Registration #12	2019-03-01	81.921 mi
Registration #13	2019-03-01	81.921 mi
Registration #14	2019-03-01	81.921 mi
Registration #15	2019-03-01	81.921 mi
Registration #16	2019-03-01	81.921 mi
Registration #17	2019-03-01	81.921 mi
Registration #18	2019-03-01	81.921 mi
Registration #19	2019-03-01	81.921 mi
Registration #20	2019-03-01	81.921 mi
Registration #21	2019-03-01	81.921 mi
Registration #22	2019-03-01	81.921 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1595 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	24586868