



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE S
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-11-14
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-11-14
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	32
Total items failed	16

MOT #19	2022-10-27 15:38
MOT test number	153858680266
Result	✓ Passed
Next expiry date	2023-11-14
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Tyre worn close to legal limit/worn on edge both rear tyres wearing on inner edges (5.2.3 (e))

**MOT #18**

2022-10-26 09:26

MOT test number

543700486784

Result

✗ Failed

Advice Tyre worn close to legal limit/worn on edge both rear tyres wearing on inner edges (5.2.3 (e))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases box (6.1.2 (a))**Fail** Front Undertray likely to become detached (6.2.1 (a) (ii))**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17**

2021-11-15 17:05

MOT test number

179401960687

Result

✓ Passed

MOT #16

2020-12-01 12:17

MOT test number

377047150431

Result

✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15** 2020-12-01 10:31**MOT test number** 418918682225**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14** 2019-06-26 15:25**MOT test number** 837144587856**Result** ✓ Passed**MOT #13** 2019-06-24 14:11**MOT test number** 453938225063**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2018-08-29 14:24**MOT test number** 496301702668**Result** ✓ Passed**MOT #11** 2018-08-29 08:29**MOT test number** 978029428333**Result** ✗ Failed**Fail** Undertray likely to become detached front belly pan (6.2.1 (a) (ii))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #10** 2017-08-24 08:13**MOT test number** 198737801011**Result** ✓ Passed**Advice** Oil leak under tray's fitted to vehicle obstructing view of some parts**Advice** Rear tyres perishing**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2016-09-08 14:49**MOT test number** 732937212196**Result** ✓ Passed**Advice** Under tray fitted to vehicle obstructing view of some parts**Advice** Oil leak**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)**Advice** Offside Rear tyre perrishing**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)**MOT #8** 2016-09-07 15:22**MOT test number** 748771038580**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)**Advice** Offside Rear tyre perrishing**Advice** Nearside Front Tyre worn close to the legal limit wearing on inner edge (4.1.E.1)**Advice** Oil leak**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)**Advice** Under tray fitted to vehicle obstructing view of some parts

**MOT #7** 2015-09-17 12:33**MOT test number** 703366545087**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-09-15 09:48**MOT test number** 736218854208**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2014-09-15 09:48**MOT test number** 998338154248**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Wheel bolt(s) missing (4.2.A.1e)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #4** 2013-09-24 11:02**MOT test number** 556777863233**Result** ✓ Passed**MOT #3** 2013-03-05 17:04**MOT test number** 825524663050**Result** ✓ Passed



MOT #2	2012-02-28 13:49
MOT test number	197569152476
Result	✓ Passed

MOT #1	2012-02-28 13:49
MOT test number	796679452070
Result	✗ Failed
<div>Pass with rectification</div> Offside Rear position lamp(s) not working (1.1.A.3b)	



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✗
MOT
Expired:
14 November 2023

Tax status	Valid until 1 November
Days left	185
MOT expiry date	14 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DU09APF
Plate since	2024-03-28
Current registration	DU09APF
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-11
Last registration	2022-10-27
Complete history	See info



Registration #1	2009-03-11	22 mi
Registration #2	2012-02-28	49.446 mi
Registration #3	2013-03-05	61.156 mi
Registration #4	2013-09-24	63.407 mi
Registration #5	2014-09-15	73.620 mi
Registration #6	2015-09-17	89.080 mi
Registration #7	2016-09-07	96.281 mi
Registration #8	2016-09-08	96.281 mi
Registration #9	2017-08-24	102.383 mi
Registration #10	2018-08-29	107.703 mi
Registration #11	2019-08-29	113.023 mi
Registration #12	2020-08-29	118.343 mi
Registration #13	2021-08-29	123.663 mi
Registration #14	2022-08-29	128.983 mi
Registration #15	2023-08-29	134.303 mi
Registration #16	2024-08-29	139.623 mi
Registration #17	2025-08-29	144.943 mi
Registration #18	2026-08-29	150.263 mi
Registration #19	2027-08-29	155.583 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	538565
---------------	--------