




report date: 2024-03-28

General information

Make	NISSAN
Model	CUBE KAIZEN
Colour	White
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	153 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	151 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-10
Pictures	29
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-21
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	25
Total items failed	15

MOT #15	2024-03-22 16:17
MOT test number	252852764054
Result	✓ Passed
Next expiry date	2025-03-21
Advice	Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2024-01-11 13:04
MOT test number	698941218688
Result	✗ Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #13** 2023-01-10 10:23**MOT test number** 581049152562**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edges (5.2.3 (e))**MOT #12** 2021-12-16 12:11**MOT test number** 833768530234**Result** ✓ Passed**Advice** Nearside Front Suspension arm damaged but not seriously weakened (5.3.3 (b) (i))**MOT #11** 2021-12-15 15:00**MOT test number** 570131923614**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Road wheel fixing missing Both (5.2.1 (a) (i))**Advice** Nearside Front Suspension arm damaged but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Anti-roll bar damaged and seriously weakened (5.3.3 (b) (i))**Fail** Road wheel fixing missing (5.2.1 (a) (i))**MOT #10** 2020-11-12 16:49**MOT test number** 298425794031**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))

**MOT #9** 2020-11-05 14:10**MOT test number** 494628545098**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Parking brake lever defective so that it cannot be satisfactorily operated no travel left (1.1.6 (d))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #8** 2019-04-05 14:58**MOT test number** 397706956480**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Slightly corroded (1.1.14 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2018-04-03 12:55**MOT test number** 152210090701**Result** ✓ Passed**MOT #6** 2018-04-03 10:48**MOT test number** 988192055445**Result** ✗ Failed**Fail** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5** 2017-08-18 13:50**MOT test number** 430268568617**Result** ✓ Passed**MOT #4** 2016-08-15 14:30**MOT test number** 661926616069**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Rear Brake pad(s) wearing thin advise replacement soon (3.5.1g)**MOT #3** 2015-08-28 09:24**MOT test number** 333214517702**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)**MOT #2** 2014-09-12 14:37**MOT test number** 996655954262**Result** ✓ Passed**Notice** O/s/f tyre has cracks/splits in inner sidewall.**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2013-10-18 09:27**MOT test number** 786031193200**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
21 March 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	VN60JXM
Plate since	2024-03-28
Current registration	VN60JXM
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-10-28
Last registration	2024-03-22
Complete history	See info



Registration #1	2010-10-28	26 mi
Registration #2	2013-10-18	31.773 mi
Registration #3	2014-09-12	38.892 mi
Registration #4	2015-08-28	47.438 mi
Registration #5	2016-08-15	52.890 mi
Registration #6	2017-08-18	62.241 mi
Registration #7	2018-04-03	66.471 mi
Registration #8	2018-04-03	66.471 mi
Registration #9	2019-04-05	76.594 mi
Registration #10	2019-04-05	76.594 mi
Registration #11	2019-04-05	76.594 mi
Registration #12	2019-04-05	76.594 mi
Registration #13	2019-04-05	76.594 mi
Registration #14	2019-04-05	76.594 mi
Registration #15	2019-04-05	76.594 mi
Registration #16	2019-04-05	76.594 mi
Registration #17	2019-04-05	76.594 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	64%
Pedestrian	56%
Safety systems	84%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1680 mm
Length	3980 mm
Wheel base	2530 mm
Kerb weight	1230 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	245005