





report date: 2024-03-29

General information

Make	NISSAN
Model	CUBE LDN
Colour	White
Year of manufacture	2011
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	153 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	151 g/km
CO2 label	G



CarCheck.co.uk page 1/11



FFZ6988 report date: 2024-03-29

Internet history

Entry	1
	-

Entry 1	
Date	2021-07-30
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



FFZ6988 report date: 2024-03-29

MOT history

MOT expiry date	2024-07-29
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #8	2023-07-11 09:20
MOT test number	555895865763
Result	✓ Passed
Next expiry date	2024-07-29
Advice Offside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))	

MOT #7		2022-07-26 09:26
MOT test	number	421582782885
Result		✓ Passed
MOT #6		2021-07-30 10:40
MOT test	number	296964182452
Result		✓ Passed
MOT #5		2021-07-30 06:49
MOT test	number	679102248290
Result		× Failed
MAJOR	Central Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Central Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #3

MOT test number

860653724955

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

126950705597

Result

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

 MOT #1
 2017-01-17 10:31

 MOT test number
 122277270695

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this NISSAN had different number plates. door of plates faste since

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2011-03-24
Last registration	2023-07-11
Complete history	See info



Registration #1	2011-03-24	13 mi
Registration #2	2017-01-17	35.419 mi
Registration #3	2019-01-05	54.022 mi
Registration #4	2020-01-07	63.175 mi
Registration #5	2020-12-22	68.673 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		111.7777 est
Registration #9		11.777 es
Registration #10		

More info >

CarCheck.co.uk page 10/11





report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	83%
Children	64%
Pedestrian	56%
Safety systems	84%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1680 mm
Length	3980 mm
Wheel base	2530 mm
Kerb weight	1230 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	52
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2
Engine number 210705