



NJ6IZVZ

report date: 2024-03-29

General information

Make	FIAT
Model	PANDA POP DUALOGIC
Colour	White
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg



LABEL UNKNOWN

**MOT history**

MOT #8	2020-01-08 14:04
MOT test number	521227504264
Result	✓ Passed
Next expiry date	2021-01-21
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front exhaust flexi poor condition
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bushes worn (5.3.4 (a) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened 2 front disc corroded and worn (1.1.14 (a) (ii))
Advice	Front exhaust bracket rotten
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement bushes deteriorating (5.3.4 (a) (i))

MOT #7	2019-01-11 10:48
MOT test number	327525099217
Result	✓ Passed

MOT #6	2019-01-10 09:42
MOT test number	771193161639
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #5	2018-01-15 12:02
MOT test number	952199040009
Result	✓ Passed
Advice	Rear exhaust outer skin deteriorated

**MOT #4** 2018-01-10 17:13**MOT test number** 656444191996**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear exhaust outer skin deteriorated**MOT #3** 2017-01-06 10:03**MOT test number** 984287596176**Result** ✓ Passed**Advice** Rear exhaust deteriorating**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2016-01-07 13:06**MOT test number** 331415141470**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-01-22 12:41**MOT test number** 935622625013**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2011-09-30
Last registration	2020-01-08
Complete history	See info



Registration #1	2011-09-30	12 mi
Registration #2	2015-01-22	15.894 mi
Registration #3	2016-01-07	23.826 mi
Registration #4	2017-01-06	33.945 mi
Registration #5	2018-01-10	45.745 mi
Registration #6	2019-01-01	55.000 mi
Registration #7	2019-01-01	55.000 mi
Registration #8	2019-01-01	55.000 mi
Registration #9	2020-01-08	55.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	6491843