



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Blue
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	141 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-08-11
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-12
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	25
Total items failed	7

**MOT #17** 2024-02-13 12:00**MOT test number** 924079451108**Result** ✓ Passed**Next expiry date** 2025-02-12**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #16** 2023-02-08 11:34**MOT test number** 233990982274**Result** ✓ Passed**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #15** 2022-02-04 10:02**MOT test number** 607760872818**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #14** 2021-02-12 11:36**MOT test number** 584545006982**Result** ✓ Passed**MOT #13** 2020-02-01 10:38**MOT test number** 156317613946**Result** ✓ Passed

- Advice** Front Brake lining(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear brakes noisy
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rusty exhaust

**MOT #12** 2020-02-01 10:38**MOT test number** 459040458504**Result** ✗ Failed

- Pass with rectification** Front Headlamp aim too low (4.1.2 (a))
- Advice** Rear brakes noisy
- Pass with rectification** Front Direction indicator incorrect colour (4.4.3 (a))
- Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Advice** Rusty exhaust
- Pass with rectification** Front Side repeater incorrect colour (4.4.3 (a))
- Advice** Front Brake lining(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2019-02-06 12:07**MOT test number** 104244548466**Result** ✓ Passed**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement bearing (5.3.4 (a) (i))**MOT #10** 2018-02-13 16:31**MOT test number** 106876411688**Result** ✓ Passed**MOT #9** 2018-02-13 09:27**MOT test number** 109353903445**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Central stop lamp not working**MOT #8** 2017-05-05 13:15**MOT test number** 170521480572**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2017-05-05 09:16**MOT test number** 138048955661**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)

**MOT #6** 2016-05-03 09:28**MOT test number** 473634249336**Result** ✓ Passed**MOT #5** 2015-05-08 11:35**MOT test number** 879518225104**Result** ✓ Passed**MOT #4** 2014-06-10 11:43**MOT test number** 826201964189**Result** ✓ Passed**Notice** Both rear tyres wearing on edges (may have been on the front at some time)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-08-28 11:52**MOT test number** 948360343202**Result** ✓ Passed**Notice** Near side rear tyre perished**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Nail in near side rear tyre**MOT #2** 2012-08-14 09:41**MOT test number** 867247822228**Result** ✓ Passed**Notice** Puncture in offside front tyre and tyre is worn below 1.6mm at inner tread area**MOT #1** 2011-08-25 09:16**MOT test number** 355477331286**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
12 February 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	12 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-11
Last registration	2024-02-13
Complete history	<a href="#">See info</a>



Registration #1	2008-09-11	10 mi
Registration #2	2011-08-25	15.572 mi
Registration #3	2012-08-14	20.665 mi
Registration #4	2013-08-28	28.654 mi
Registration #5	2014-06-10	33.002 mi
Registration #6	2015-05-08	33.313 mi
Registration #7	2016-05-03	38.236 mi
Registration #8	2017-05-05	44.931 mi
Registration #9	2017-05-05	44.935 mi
Registration #10	2018-02-13	49.741 mi
Registration #11	2019-05-05	55.557 mi
Registration #12	2020-05-05	61.373 mi
Registration #13	2021-05-05	67.189 mi
Registration #14	2022-05-05	73.005 mi
Registration #15	2023-05-05	78.821 mi
Registration #16	2024-02-13	84.637 mi
Registration #17	2024-02-13	84.637 mi
Registration #18	2024-02-13	84.637 mi
Registration #19	2024-02-13	84.637 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1025 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4EE8070157