



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T32 LWB PBV 102TDI E4
Colour	Silver
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	18.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 2.000 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	39.8 mpg
Consumption combined	34.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-27
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-19
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	42
Total items failed	10

MOT #18	2023-10-17 08:43
MOT test number	331857868830
Result	✓ Passed
Next expiry date	2024-10-19
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2022-10-20 13:23
MOT test number	419108027594
Result	✓ Passed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #16**

2021-11-09 13:34

MOT test number

940667511283

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Windscreen wiper blade defective (3.4 (b) (i))**Advice** Front Outer Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2020-11-17 08:01

MOT test number

196281727814

Result

✓ Passed

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #14**

2020-11-13 12:58

MOT test number

954208799207

Result

✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #13** 2019-11-20 09:12**MOT test number** 855337624180**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm 205/65 R16c (5.2.3 (e))**Advice** Rear Inner Brake pad(s) wearing thin both side (1.1.13 (a) (ii))**MOT #12** 2019-11-20 09:12**MOT test number** 368036336507**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm 205/65 R16c (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Inner Brake pad(s) wearing thin both side (1.1.13 (a) (ii))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #11** 2018-11-20 09:59**MOT test number** 278432628772**Result** ✓ Passed**MOT #10** 2017-11-27 12:01**MOT test number** 500818986025**Result** ✓ Passed**MOT #9** 2016-10-25 09:46**MOT test number** 185582414310**Result** ✓ Passed

**MOT #8**

2015-11-17 09:54

MOT test number

874993280815

Result

✓ Passed

- Advice** Exhaust box is corroded
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened Lipped & corroded (3.5.1i)
- Advice** Spare carrier one bolt is missing
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened lipped & corroded (3.5.1i)
- Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2)
- Advice** Multi purpose vehicle

MOT #7

2014-12-12 12:11

MOT test number

157386644367

Result

✓ Passed

- Notice** R/discs badley corroded

MOT #6

2014-12-11 10:28

MOT test number

655895344324

Result

✗ Failed

- Fail** Offside Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
- Notice** R/discs badley corroded
- Fail** Nearside Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
- Fail** Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #5** 2014-12-11 10:19**MOT test number** 816935944373**Result** ✗ Failed**Fail** Offside Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)**Notice** Note r/discs badly corroded outer edges**Fail** Nearside Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)**MOT #4** 2014-01-07 15:20**MOT test number** 555087104081**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Notice** Handbrake micro-switch repaired but serviceable**MOT #3** 2013-01-09 15:31**MOT test number** 148549803073**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2012-01-11 09:42**MOT test number** 985011112040**Result** ✓ Passed



MOT #1	2012-01-11 09:42
MOT test number	116271112486
Result	✗ Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)
Pass with rectification	Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
19 October 2024

Tax status		Valid until 1 September
Days left		126
MOT expiry date		19 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 OV58YHT
Plate since	2024-03-28
Current registration	 OV58YHT
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-12-17
Last registration	2023-10-17
Complete history	See info



Registration #1	2008-12-17	27 mi
Registration #2	2012-01-11	56.863 mi
Registration #3	2013-01-09	77.497 mi
Registration #4	2014-01-07	90.181 mi
Registration #5	2014-12-11	98.741 mi
Registration #6	2014-12-11	98.741 mi
Registration #7	2014-12-12	98.741 mi
Registration #8	2015-11-17	106.310 mi
Registration #9	2016-10-25	115.868 mi
Registration #10	2017-11-27	129.259 mi
Registration #11	2018-05-22	151.377 mi
Registration #12	2018-05-22	151.377 mi
Registration #13	2018-05-22	151.377 mi
Registration #14	2018-05-22	151.377 mi
Registration #15	2018-05-22	151.377 mi
Registration #16	2018-05-22	151.377 mi
Registration #17	2018-05-22	151.377 mi
Registration #18	2018-05-22	151.377 mi
Registration #19	2018-05-22	151.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2242 mm
Height	1969 mm
Length	5290 mm
Kerb weight	1849 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	BRS 087291