



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-26
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	58
Total items failed	6

MOT #16 2024-03-21 12:49

MOT test number 744869230092

Result ✓ Passed

Next expiry date 2025-03-26

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Inner sidewall (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Outer Drive shaft joint constant velocity boot severely deteriorated Loose but preventing the ingress of dirt (6.1.7 (g) (i))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords Inner sidewall (5.2.3 (d) (i))

MOT #15 2023-03-27 11:45

MOT test number 217604841919

Result ✓ Passed

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2023-03-27 09:24

MOT test number

318471986407

Result

✗ Failed

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13

2022-03-22 16:49

MOT test number

591360895761

Result

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2022-03-14 15:52

MOT test number

236994463886

Result**✗ Failed****Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice

Coolant level below minimum mark

MAJOR

Front Exhaust system insecure and middle clamp detached. (6.1.2 (a))

Advice

Front Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))

Advice

Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11

2021-03-26 15:16

MOT test number

561650694545

Result**✓ Passed****Advice**

Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice

Front Tyre worn close to legal limit/worn on edge o/s & n/s (5.2.3 (e))

MOT #10

2021-03-20 12:23

MOT test number

606333602151

Result**✗ Failed****MAJOR**

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR

Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice

Front Tyre worn close to legal limit/worn on edge o/s & n/s (5.2.3 (e))

**MOT #9** 2020-11-27 12:16**MOT test number** 894234132022**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing inner sidewall (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-10-21 13:09**MOT test number** 966305081057**Result** ✓ Passed**MOT #7** 2019-10-21 10:06**MOT test number** 227363195497**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2018-10-17 07:54**MOT test number** 467100493617**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-10-11 09:10**MOT test number** 961518789716**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Pass with rectification** Offside Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))**MOT #4** 2017-10-13 08:55**MOT test number** 596985406024**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Sill and under trays fitted not allowing full inspection.**MOT #3** 2017-09-29 09:07**MOT test number** 107018808812**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Stop lamp remains on when the brakes are released bulb fitted incorrectly. (1.2.1e)**Advice** Sill and under trays fitted not allowing full inspection.**Fail** Exhaust system not adequately supported front and rear. (7.1.1)



MOT #2	2016-11-23 10:52
MOT test number	138006691680
Result	✓ Passed
Advice	Central Front exhaust mounts corroded from exhaust pipe.
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Central Front Lower under trays fitted to vehicle.

MOT #1	2015-11-26 10:07
MOT test number	955511225522
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Under trays and cill covers fitted not allowing full inspection.



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
26 March 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	PK62RXB
Plate since	2024-03-29
Current registration	PK62RXB
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-11-09
Last registration	2024-03-21
Complete history	See info



Registration #1	2012-11-09	21 mi
Registration #2	2015-11-26	54.740 mi
Registration #3	2016-11-23	59.351 mi
Registration #4	2017-09-29	64.407 mi
Registration #5	2017-10-13	64.529 mi
Registration #6	2018-10-11	73.501 mi
Registration #7	2018-10-17	73.504 mi
Registration #8	2019-10-21	77.635 mi
Registration #9	2019-10-21	77.635 mi
Registration #10	2019-10-21	77.635 mi
Registration #11	2019-10-21	77.635 mi
Registration #12	2019-10-21	77.635 mi
Registration #13	2019-10-21	77.635 mi
Registration #14	2019-10-21	77.635 mi
Registration #15	2019-10-21	77.635 mi
Registration #16	2019-10-21	77.635 mi
Registration #17	2019-10-21	77.635 mi
Registration #18	2019-10-21	77.635 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEF3023664