





General information

Make	AUDI
Model	A3 TDI SPORT
Colour	Black
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Power	103 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В





Internet history	
Entry 1	
Date	2021-01-27
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-10
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	39
Total items failed	14

MOT #13		2024-04-11 12:36
MOT test	number	255108184419
Result		✓ Passed
Next expi	ry date	2025-04-10
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing heavily cracking t	tread (5.2.3 (d) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn low /heavily xposing ply (5.2.3 (e))	worn inner shoulder
Advice	Offside Rear Tyre slightly damaged/cracking or perishing heavily cracking tre	ead (5.2.3 (d) (ii))
Advice deteriorate	Offside Front Suspension arm pin or bush worn but not resulting in excessive ed (5.3.4 (a) (i))	e movement rear bush
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn low /heavily w xposing ply (5.2.3 (e))	vorn inner shoulder
Advice	Offside Front Brake pad(s) wearing thin worn close to minimum thickness (1.	1.13 (a) (ii))





MOT #12	2024-04-08 09:10
MOT test number	295196228480
Result	🗙 Failed
Advice Offside Front Brake pad(s) wearing thin worn close to minimum thickness (1.1.13	3 (a) (ii))
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b)	(ii))
Fail (ii))Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingres	s of dirt (5.3.4 (b)
Advice Nearside Rear Tyre slightly damaged/cracking or perishing heavily cracking trea	d (5.2.3 (d) (ii))
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn low /heavily wor close to exposing ply (5.2.3 (e))	rn inner shoulder
Advice Offside Rear Tyre slightly damaged/cracking or perishing heavily cracking tread	(5.2.3 (d) (ii))
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive modeleriorated (5.3.4 (a) (i))	ovement rear bush
Fail (b) (ii))Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingre	ess of dirt (5.3.4
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge worn low /heavily worn close to exposing ply (5.2.3 (e))	inner shoulder

MOT #11	2023-03-31 07:16
MOT test number	664618838004
Result	✓ Passed

MOT #10	2023-03-25 14:16
MOT test number	933780161215
Result	🗙 Failed
Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no lo ingress of dirt (6.1.7 (g) (ii))	onger prevents the
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to (5.2.3 (d) (i))	reach the ply or cords
Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no lon of dirt (6.1.7 (g) (ii))	ger prevents the ingress

CarCheck.co.uk



FR62EZG
report date: 2024-03-28

MOT #9		2022-03-17 10:47
MOT test	number	582557108968
Result		✓ Passed
Advice	Front screen marked	
Advice	Nearside Non obligatory mirror damaged	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside wing mirror secured with tape	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #8	2022-03-15 09:32
MOT test number	396297813150
Result	× Failed
Advice Front screen marked	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Offside wing mirror secured with tape	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Offside Side repeater not working wing mirror repeater (4.4.1 (a) (ii))	
Advice Nearside Non obligatory mirror damaged	





MOT #7		2021-03-10 10:04
MOT test	number	413562741186
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
Advice	Light scratch on windscreen	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	N/s/f tyre incorrectly fitted inside/outside	

MOT #6		2020-02-21 16:10
MOT test	number	948181294208
Result		✓ Passed
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Rear x2 tyres slight misshape inner edges	
Advice	Front Tyre worn close to legal limit/worn on edge x2 inner edges o/s LIMITS!!	(5.2.3 (e))
Advice (a) (i))	Front Suspension arm pin or bush worn but not resulting in excessive movem	ent n/s and o/s (5.3.4
Advice	Nearside Front tyre perished	

MOT #5	2019-04-12 15:58
MOT test number	378288040646
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge x2 LIMITS!! (5.2.3 (e))	

MOT #4	2018-04-13 13:30
MOT test number	134140797909
Result	✓ Passed





MOT #3	3	2018-04-12 15:34
MOT te	st number	951175816933
Result		🗙 Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Rear Brakes imbalanced across an axle (3.7.B.5b)	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Front Brakes imbalanced across an axle (3.7.B.5b)	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #2	2017-02-10 15:48
MOT test number	618991330684
Result	✓ Passed

MOT #1	2016-03-09 17:38
MOT test number	749746872136
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

Tax due: 1 April 2025	√ Taxed	Expires: 10 April 2025	✓ МОТ
Tax status			Valid until 1 April
Days left			337
MOT expiry date			10 April 2025
Full MOT history			<u>See MOT history</u>
Tax calculation			
Vehicle class		49	
		-	

Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et a
Date	*
Category	AMP
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-01-29
Last registration	2024-04-11
Complete history	See info



Registration #1	2013-01-29	13 mi
Registration #2	2016-03-09	55.209 mi
Registration #3	2017-02-10	57.210 mi
Registration #4	2018-04-12	61.232 mi
Registration #5	2018-04-13	61.232 mi
Registration #6	2019-04-12	77.343 mi
Registration #7	2020-02-21	85.175 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	95%
Children	87%
Pedestrian	74%
Safety systems	86%
Overall rating	88%
Video	see crash video



Dimensions & weight	
Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles	2
Engine number	CAYCR85129